

2019 MAZDA Mazda3 Sedan XD Proactive		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE BP8P	DISPLACEMENT 1,756 cc		
YEAR / REG. 2019/09	MILEAGE 92,790 km		
DOORS 4	SEATS 5		
TRANSMISSION AT	FUEL Diesel		
STEERING Right	EXTERIOR COLOR Blue		
BODY TYPE Sedan			
CHASSIS NO. BP8P-103875	DIMENSIONS (L X W X H) 466 × 180 × 145 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control 360° Camera Mazda Harmonic Acoustics (8 speakers)		Pre-Collision Braking Back Camera Navigation System	
INSPECTOR REPORT			
Right front inside panel distortion, exterior scratches.			

ORIGINAL JAPANESE AUCTION SHEET

年式 R1 / 9月	メーカー マツダ	ドア数 4	ボディ形状 セダン	評価点 R
車名 MAZDA 3 セダン	グレード XD プロアクティブ	駆動方式 2WD	燃費区分 4WD	
車種 自家用・その他 ()	排気量 1800 cc	形式 BP8P	国産 A・⑨・C	
登録 - 年 - 月 / 日	ガソリン ハイブリッド ()	後付選り品 (保証書・取扱説明書等)		
走行 92,790 km	フロア 6 AT			
外装色 ディーブルスブルーマイカ (42M)	カラーNo.	エンジン QD・AAG・WAG ()	装備品のみ C印 を記入	
()	内装色	乗車定員 5 人	サンルーフ	革シート
左・()	輸入 ディーラー・直行	9,490円・現行税	エレクトロ	その他
セールスポイント		修復歴 ⑨・無		
純正ナビ フルセグBluetooth バックカメラ 衝突軽減ブレーキレーンアシスト レーダークルーズコントロール クリアランスソナー ブラインドスポットモニター ヘッドアップディスプレイ				
検査記入欄		A サイズ U ハコボネサレ B サイズハコボネ P 色あせ・汚れ G ガラスキズ		
右Fインサイドパネル歪み 外装線傷		W 経年劣化 S サイズ C 腐食 X 交換車 XX 交換車		
		名義中		
		月 日 までに名義できる方		
		車体番号 BP8P-103875		
FR	FL	PR	PL	小
内装	外装	サブリ	コグス	オーディー
ス	ス	ス	ス	ス
cm	cm	cm	cm	kg