

2019 MercedesBenz Benz B Class B180 AMG Line		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 247084	DISPLACEMENT 1,331 cc		
YEAR / REG. 2019/07	MILEAGE 28,528 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Minivan		
CHASSIS NO. WDD2470842J038360	DIMENSIONS (L X W X H) 443 × 180 × 155 cm		
SALES POINTS			
Alloy Wheels Leather Seats Power Seats (Front) Parking Assist (Auto Steering) Adaptive Cruise Control 360° Camera		Sunroof Power Tailgate Cruise Control Back Camera Front Camera Navigation System	
INSPECTOR REPORT			
Exterior: minor scratches and minor dents/unevenness. Interior: dirt/stains.			

年式登録番号	メルセデス・ベンツ	ドア数	5	ボディ形状	ミニバンワンボックス	特種車種																																												
R1 / 7月	Bクラス	グレード	B180 ライン	駆動方式	2WD 4WD	4																																												
車種	自家用・その他()	排気量	1300	形式	2470B4	国産																																												
車検	- - 年	燃料	ガソリン	ディーゼル	後付選り品 (保証書・取扱説明書等)	A・C																																												
走行	(内記にマークを記入(入・交換)※(点検)※(年換))	シフト	オートマチック	マニュアル																																														
外装色	カラーNo.	モデル	フロア 7 AT																																															
ボラーホワイト	()	内装色	QD・AAG・WAG・()																																															
左・中・右	G	乗車定員	5人																																															
左・中・右	G	リサイクル料	19,130円																																															
セールスポイント																																																		
パノラミックスライディングルーフ AMGレザークラスクーシェイプPKG アドバンスDPKG 本革シート アンビエントライト 360°カメラ ヘッドアップディスプレイ パワーバックドア AMG18アルミ																																																		
検査記入欄																																																		
外装小A小U																																																		
修復歴																																																		
有、⑤																																																		
<table border="1"> <thead> <tr> <th>W</th> <th>N</th> <th>キズ</th> <th>U</th> <th>へこみ凹み</th> <th>P</th> <th>キズへこみ</th> <th>F</th> <th>熱変形・割れ</th> <th>G</th> <th>ガラス欠損</th> </tr> </thead> <tbody> <tr> <td>腐蝕</td> <td>錆</td> <td>S</td> <td>サビ</td> <td>C</td> <td>変質</td> <td>X</td> <td>交換済</td> <td>XX</td> <td>交換済</td> <td></td> </tr> <tr> <td colspan="10"></td> <td>名義ノ</td> </tr> <tr> <td colspan="10"></td> <td>月 日 家でどこ名で販売するか</td> </tr> </tbody> </table>							W	N	キズ	U	へこみ凹み	P	キズへこみ	F	熱変形・割れ	G	ガラス欠損	腐蝕	錆	S	サビ	C	変質	X	交換済	XX	交換済												名義ノ											月 日 家でどこ名で販売するか
W	N	キズ	U	へこみ凹み	P	キズへこみ	F	熱変形・割れ	G	ガラス欠損																																								
腐蝕	錆	S	サビ	C	変質	X	交換済	XX	交換済																																									
										名義ノ																																								
										月 日 家でどこ名で販売するか																																								
車体番号 WDD2470B4Z1 038360																																																		
シリアル No.																																																		
製造																																																		
最大積載量																																																		