

2019 MINI Crossover Cooper D Crossover		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE YT20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2019/11	MILEAGE 88,746 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Hatchback		
CHASSIS NO. WMWYT920403H98108	DIMENSIONS (L X W X H) 432 × 182 × 160 cm		
SALES POINTS			
Alloy Wheels Power Tailgate Adaptive Cruise Control Navigation System		Roof Rails Pre-Collision Braking Back Camera	
INSPECTOR REPORT			
Exterior: Small scratches, small dents. Interior: Small scratches, small dirt.			

新年度登録	メーカー MINI	ドア数 5	ボディ形状 コンパクトハッチバック	評価値 9.0
R1 / 11月	車名 MINI	グレード クーパーDクロス オーバー	燃費区分 2WD 4WD	4.5
車種 自動車・その他（ ）	排気量 2000 CC	型式 YT20	運転形式	内装 A・⑨・C
年次 8年11月抜済	燃料 ガソリン ハイブリッド（ ）	式 モーター	後付選り品（保証書・取扱説明書等）	
走行 10万にマークを記入（左・右両方）※（途中のみ・安全）	マイル 88746	シフト フロア AT		
外装色 ブラック	カラーメタ (A94)	エンジン AG・WAG・()	装備品のO印を記入	
()	内装色	乗車定員 5人		
方向 左・右	輸入国 ドイツ	走行 リサイクル料	価格 19,090円・税別	
セールのポイント				
★ユーザー買取車 ★LEDヘッド ★バックカメラ ★18インチAW ★ルーフレール ★パワーバックドア ★革調シートカバー				
検査記入欄				
外装 小キズ、小へこみ 内装 小キズ、小ヨゴレ				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				
 検査点 有。●				