

2019 MITSUBISHI Delica D5 G		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3DA-CV1W	2,267 cc		
YEAR / REG.	MILEAGE		
2019/10	107,032 km		
DOORS	SEATS		
5	7		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Other	Minivan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
CV1W-2115423	480 × 180 × 188 cm		
SALES POINTS			
Alloy Wheels		Leather Seats	
Power Sliding Doors (Both Sides) (Both...		Pre-Collision Braking	
Adaptive Cruise Control			
INSPECTOR REPORT			
Squeaking sound detected, equipped with studless tires and 4 aftermarket wheels, interior has seat scuffs, steering wheel scuffs, dirt, and stains, exterior shows minor trim damage (A), minor paint damage (A), cracked aero parts, and front windshield stone chips, undercarriage has rust/corrosion (S), wheels are bent and cracked, flip-down monitor is faulty, and an audio system hole is present.			

[illegible]