

2019 MITSUBISHI ek Wagon M		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-B33W	DISPLACEMENT 659 cc		
YEAR / REG. 2019/05	MILEAGE 68,100 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Kei		
CHASSIS NO. B33W-0003258	DIMENSIONS (L X W X H) 340 × 148 × 164 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Rear tailgate removed/reinstalled, left side repair marks, wheel cap minor scratches.			

ORIGINAL JAPANESE AUCTION SHEET

R1 / 5月		三菱		ドア枚数 5		ボディ構造 軽四		評価点 4																					
車名 eKワゴン		グレード M		駆動区分 2WD		4WD																							
車種 自家用・その他 ()	排気量 660 cc	型式 5BA-B33W	通称 型式	内装 A・⑨・C																									
車検 - - 年 月	燃料 ガソリン	ディーゼル	後日送り品 (保証書・取扱説明書等)																										
走行 68,100 km	シフト インパネ	CVT																											
外装色 シルバー	カラーNo. U25	エアコン	新着品のみ O印 を記入																										
内装色	乗車定員 4人	AW	サンルーフ	革シート																									
左・右	輸入区分	ディーラー	並行	リサイクル料	8,700円	預託金	エアコン	ABS	GPS	TV	モース																		
セールスポイント																													
キーレス・スベアーキー有 CD・AM・FMラジオ シートヒーター					修復歴 有・⑨																								
検査記入欄					<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>					A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ/ボケ	G	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																				
リヤゲート脱着					登録No. 月 日 までに名変できる方																								
左側面補修跡					名変中																								
ホイールキャップA					車検 339 cm 幅 147 cm 高さ 164 cm 最大積重量 Kg																								
FW トビ石 傷A フレ 外装 小・中・大																													
内装 ヨゴレ シミ ヤブレ コゲ コゲ穴 オーディオ穴 スレ																													