

2019 Nissan Dayz Roox X		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-B21A	659 cc		
YEAR / REG.	MILEAGE		
2019/03	39,056 km		
DOORS	SEATS		
5	4		
TRANSMISSION	FUEL		
AT	Petrol		
STEERING	EXTERIOR COLOR		
Right	Black		
BODY TYPE			
Kei			
CHASSIS NO.	DIMENSIONS (L X W X H)		
B21A-0563320	340 × 148 × 178 cm		
SALES POINTS			
Pre-Collision Braking		Front Camera	
Side Camera		Back Camera	
Navigation System			
INSPECTOR REPORT			
Steering wheel wear, end panel U2, rear gate not opening			

初年度登録	メーカー 日産	ドア数 5	ボディ形状 軽四	年価点 10																				
H31 / 3月	車名 デイズルークスX		グレード X	駆動方式 2WD 4WD	9 3.5																			
車種 乗用車・その他（ ）	排気量 660 CC	型式 DBA-B21A	温熱処理 普通	内装 A・B・G																				
実売 10年3月	扶消 料	燃料 ハイブリッド	ディーゼル エンジン	最低月間納付金（保証費・取扱説明書等）																				
走行 3万9千056km	インパネ	AT																						
外装色 ブラック	カラーNo. X42	エディション AD・AWD・WAG・（ ）																						
()	内装色 標準装備	最大定員 4人																						
ナビ 左・前 輸入 区分	ディーラー 販売	リサイクル料 8,230円	関係税 エコノミクス	ABS																				
セールスポイント																								
ナビ、フルセグTV、全周囲カメラ、パワースライドドア																								
検査記入欄		修復歴 有：(G) 有：(G)																						
ハンドルスレ、エンドパネルU2、リアゲート開かず		<table border="1"> <thead> <tr> <th>A</th> <th>キズ</th> <th>U</th> <th>へこみサシ</th> <th>B</th> <th>キズへこみ</th> <th>P</th> <th>色あせ・汚れ</th> <th>G</th> <th>ガラスキズ</th> </tr> </thead> <tbody> <tr> <td>W</td> <td>修繕跡</td> <td>S</td> <td>サビ</td> <td>C</td> <td>腐食</td> <td>X</td> <td>交換済</td> <td>XXI</td> <td>交換済</td> </tr> </tbody> </table>			A	キズ	U	へこみサシ	B	キズへこみ	P	色あせ・汚れ	G	ガラスキズ	W	修繕跡	S	サビ	C	腐食	X	交換済	XXI	交換済
A	キズ	U	へこみサシ	B	キズへこみ	P	色あせ・汚れ	G	ガラスキズ															
W	修繕跡	S	サビ	C	腐食	X	交換済	XXI	交換済															
登録年月日		令和元年 月 日																						
車体番号		B21A-0563320																						
FW	シボ	シボ	フレ	外装	小	ホイール	エアロ	シリアル																
内装	シボ	シボ	フレ	コグ	コグ	オーデイオ	オーディオ	車両																