

2019 Nissan Dayz Roox X		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE B21A	DISPLACEMENT 659 cc		
YEAR / REG. 2019/09	MILEAGE 40,823 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Black		
BODY TYPE Kei			
CHASSIS NO. B21A-0603145	DIMENSIONS (L X W X H) 340 × 148 × 178 cm		
SALES POINTS			
Power Sliding Doors (Both Sides) (Drive...		Pre-Collision Braking	
Front Camera		Side Camera	
Back Camera		360° Camera	
Navigation System			
INSPECTOR REPORT			
Mirror paint peeling, small scratch (A) on mirror, small stain on seat, small scratch (A) on console, rear bumper dented, headlights cloudy, wheel cover scratch (A).			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 R1	メーカー 日産	ドア数 5	ボディ形状 軽四	評価点 4
9月	車名 デイズルークスX	グレード 2WD	駆動区分 4WD	
車種 自家用・その他 ()	排気量 660 cc	型式 B21A	登録区分 A・⑤・C	
年 月 日	燃料 ガソリン	ディーゼル	後付選用品 (保証書・取扱説明書等)	
走行 40,823 km	インパネ	AT		
外装色 アメジストブラックパール	カラーNo.	エアコン	新着品のみ・O印を記入	
内装色	乗車定員 4人	AW	サンルーフ	革シート
左・右 左・右	ディーラー	走行	8,230円	販売額
セールスポイント				
バックカメラ/ETC/横滑り防止装置 (ESC)/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/A B S /助手席エアバック/サイドエアバック/メモリーナビ他/ワンセグTV/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/全周囲カメラ/フロントカメラ/サイドカメラ				
検査記入欄				
ミラー-塗装剥れ シート-シミ・小穴 コンソール-A・小穴 B/バンパー-絆され ヘッドライト-くもり ホイール-カバー-A				
A1 A2 A1 A1 A2 B1 A1 A2 修復歴 有・⑥				
A キズ B ヘッドライト C サブ D 腐食 E 変色 F 変色 G ガラスキズ W 変色 H サブ C 腐食 X 変色 Y 変色 Z 変色				
名義中 月 日 まで				
B21A-0603145				
車種 軽四				
全長 340 cm 全幅 148 cm 全高 178 cm 最大積載量 400 kg				