

|                                                                                                                                          |                        |                       |          |
|------------------------------------------------------------------------------------------------------------------------------------------|------------------------|-----------------------|----------|
| 2019 PEUGEOT 3008 GT BlueHDi                                                                                                             |                        | OVERALL               |          |
|                                                                                                                                          |                        | 4                     |          |
|                                                                                                                                          |                        | EXTERIOR              | INTERIOR |
|                                                                                                                                          |                        | -                     | -        |
| MODEL CODE                                                                                                                               | DISPLACEMENT           |                       |          |
| LDA-P84AH01                                                                                                                              | 1,997 cc               |                       |          |
| YEAR / REG.                                                                                                                              | MILEAGE                |                       |          |
| 2019/06                                                                                                                                  | 58,326 km              |                       |          |
| DOORS                                                                                                                                    | SEATS                  |                       |          |
| 5                                                                                                                                        | 5                      |                       |          |
| DRIVETRAIN                                                                                                                               | TRANSMISSION           |                       |          |
| 2WD (FF)                                                                                                                                 | AT                     |                       |          |
| FUEL                                                                                                                                     | STEERING               |                       |          |
| Diesel                                                                                                                                   | Right                  |                       |          |
| EXTERIOR COLOR                                                                                                                           | BODY TYPE              |                       |          |
| Other                                                                                                                                    | SUV                    |                       |          |
| CHASSIS NO.                                                                                                                              | DIMENSIONS (L X W X H) |                       |          |
| VF3MJEHZRKS175038                                                                                                                        | 445 × 186 × 163 cm     |                       |          |
| SALES POINTS                                                                                                                             |                        |                       |          |
| Alloy Wheels                                                                                                                             |                        | Roof Rails            |          |
| Power Tailgate                                                                                                                           |                        | Pre-Collision Braking |          |
| Adaptive Cruise Control                                                                                                                  |                        | Side Camera           |          |
| Back Camera                                                                                                                              |                        | Front Camera          |          |
| Navigation System                                                                                                                        |                        |                       |          |
| INSPECTOR REPORT                                                                                                                         |                        |                       |          |
| Steering wheel wear, trim scratches and dirt, seat wear, wrinkles and dirt, stone chips on the front, minor body scratches, hood fading. |                        |                       |          |

[illegible]