

2019 PEUGEOT PEUGEOT 308 5HB GT Line BlueHDi		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE T9YH01	DISPLACEMENT 1,498 cc		
YEAR / REG. 2019/06	MILEAGE 66,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Hatchback		
CHASSIS NO. VF3LBYHZRKS093708	DIMENSIONS (L X W X H) 428 × 181 × 147 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control Back Camera		Pre-Collision Braking Parking Assist (Auto Steering) Navigation System	
INSPECTOR REPORT			
Exterior: Noticeable scratches and dents have been repaired, but minor scratches and dents remain. Interior: Some noticeable stains are present in parts. Repair History: No abnormalities in the frame.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグレード鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 R1/6月	メーカー プジョー	ドア数 5	ボディ形状 コンパクトハッチバック	評価点 4
車名 308	グレード GTライン	ブルーHDi		
用途 自家用	ディーラー 右	型式 T9YH01	登録年 1500	ディーゼル B
年 -	月 -	日 -	走行 66,000	マイル 66,000
色 ブルー	カラーNo. ()	リサイクル料 18,560円	車両番号 VF3LBYHZRKS093708	
シフト フロア 8 AT	乗車定員 5人	長さ 428cm	幅 181cm	高さ 147cm

車検返却日
(保証書・取説説明書等)

整備
エンジン
変速機
サスペンション
ブレーキ

セールスポイント

査定員記入欄

※ダメージレベルに関する注意事項
ダメージレベルは、車両の損傷状況を評価するための指標です。ダメージレベルは、車両の損傷状況を評価するための指標です。ダメージレベルは、車両の損傷状況を評価するための指標です。

クオリティグレード説明
外装: 劣化するキズやヘコミは補修済みですが、小さなキズやヘコミが残っています。
内装: 劣化する汚れ等が、部分的にあります。

修理歴: 青枠部位に異常はありません。

車両状態の図解

グレード鑑定 コンディションチェックシート

査定日: 2020年06月12日

内蔵定尺

クオリティグレード

外装

内装

エンジン

変速機

サスペンション

ブレーキ

ボディ

ドア

ガラス

タイヤ

ホイール

その他

査定員

査定日

査定場所

査定時間

査定金額

査定コメント