

2019 Porsche PANAMERA Turbo		OVERALL 3.5	
		EXTERIOR -	INTERIOR -
MODEL CODE ABA-G2J40A	DISPLACEMENT 3,996 cc		
YEAR / REG. 2019/12	MILEAGE 60,600 km		
DOORS 5	DRIVETRAIN 4WD		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Gray		
BODY TYPE Sedan			
CHASSIS NO. WPOZZZ97ZJL142453	DIMENSIONS (L X W X H) 505 × 194 × 143 cm		
SALES POINTS			
Alloy Wheels Power Tailgate Cruise Control Front Camera BOSE (710W14SP)		Leather Seats (Leather) Power Seats (Front) Back Camera Navigation System	
INSPECTOR REPORT			
Light stains on seats, warped right baffle			

初年度登録	メーカー ボルシェ	ドア数 5	ボディタイプ セダン	駆動形式 FF																																								
R1 12月	車名 パナメーラ	グレード ターボ	燃費 2WD 100	3.5																																								
車種 自動車	用途 その他	排気量 4000 cc	型式 ABA-GJZ 40A	国産 A・C																																								
車検 - 年 6 月 00 日	燃料 ガソリン	ディーゼル ハイブリッド	後付選付品 (保証書・取扱説明書 等)																																									
走行 10000 km	シフト フロア 8 AT																																											
外装色 グレー	カラーNo. AD・WD・WAC・C	新車品のみ O印を記入																																										
内装色 ()	標準定員 人	サンルーフ ☐ 電動 ☐																																										
左・前・後 左・前・後	走行 31,610 円	オプション エアロ																																										
セールスポイント																																												
★21AW ★BOSEサウンド ★カーボンインテリア ★レッドキャリパー ★アルバインTVチューナー																																												
修復歴 有 ☒																																												
検査記入欄																																												
シートウオッシュ 右パッフル歪																																												
<table border="1"> <tr> <td>A</td> <td>キズ</td> <td>U</td> <td>へこみ割伤</td> <td>B</td> <td>キズへこみ</td> <td>P</td> <td>色あせ・汚れ</td> <td>G</td> <td>ガラスキズ</td> </tr> <tr> <td>W</td> <td>腐蝕</td> <td>S</td> <td>サビ</td> <td>C</td> <td>変色</td> <td>X</td> <td>変形</td> <td>XX</td> <td>欠陥</td> </tr> <tr> <td colspan="9"></td> <td>名義</td> </tr> <tr> <td colspan="9">月 日</td> <td>家でどこまでできる</td> </tr> </table>					A	キズ	U	へこみ割伤	B	キズへこみ	P	色あせ・汚れ	G	ガラスキズ	W	腐蝕	S	サビ	C	変色	X	変形	XX	欠陥										名義	月 日									家でどこまでできる
A	キズ	U	へこみ割伤	B	キズへこみ	P	色あせ・汚れ	G	ガラスキズ																																			
W	腐蝕	S	サビ	C	変色	X	変形	XX	欠陥																																			
									名義																																			
月 日									家でどこまでできる																																			
車検番号 WP 0ZZ297J L142453																																												
<table border="1"> <tr> <td>FW</td> <td>トビ足</td> <td>傷A</td> <td>フレ</td> <td>内装</td> <td>小</td> <td>オイル</td> <td>エアロ</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Q・U</td> <td>Q・油</td> <td>シリアル</td> </tr> <tr> <td>内装</td> <td>Q・U</td> <td>シロ</td> <td>ヤレ</td> <td>コガ</td> <td>コガ</td> <td>コガ</td> <td>最大積載量</td> </tr> </table>					FW	トビ足	傷A	フレ	内装	小	オイル	エアロ						Q・U	Q・油	シリアル	内装	Q・U	シロ	ヤレ	コガ	コガ	コガ	最大積載量																
FW	トビ足	傷A	フレ	内装	小	オイル	エアロ																																					
					Q・U	Q・油	シリアル																																					
内装	Q・U	シロ	ヤレ	コガ	コガ	コガ	最大積載量																																					