

2019 Subaru Levorg 1.6 STI Sport EyeSight Black Selection

OVERALL

4.5

EXTERIOR

-

INTERIOR

-

MODEL CODE

DBA-VM4

DISPLACEMENT

1,599 cc

YEAR / REG.

2019/06

MILEAGE

62,100 km

DOORS

5

SEATS

5

DRIVETRAIN

4WD

TRANSMISSION

AT

FUEL

Petrol

STEERING

Right

EXTERIOR COLOR

Black

BODY TYPE

Station Wagon

CHASSIS NO.

VM4-140578

DIMENSIONS (L X W X H)

469 × 178 × 149 cm

SALES POINTS

Alloy Wheels

Leather Seats (Ultrasuede, Leather)

Adaptive Cruise Control

Front Camera

Back Camera

Power Seats (Front)

Pre-Collision Braking

Cruise Control

Side Camera

Navigation System

INSPECTOR REPORT

Minor scratches, minor dents

ORIGINAL JAPANESE AUCTION SHEET

年式登録番号 R1 / 6月	メーカー スバル レヴォーグ	ドア数 5	ボディ形状 ステーションワゴン	評価点 4.5
車種 自家用・その他 ()	排気量 1600 cc	型式 DBA-VM4	登録区分 2WD	内装 A・⑤・C
車検 - - 年 / 月 / 日	燃料 ガソリン	ディーゼル	後付選用品 (保証書・取扱説明書等)	
走行 62,100 km	フロア	AT		
外装色 クリスタルブラックシリカ	カラーNo.	エアコン	装備品のみ・O印を記入	
()	内装色	5人	サンルーフ 革シート	
左・前・後 13,610円	ディーラー	走行	エレクトロニクス	
セールスポイント				
パワーシート/CD/フルフラットバックカメラ/ETC/横滑り防止装置 (ESC)/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/A B S/助手席エアバック/サイドエアバック/メモリーナビ他/フルセグTV/衝突被害軽減ブレーキ/衝突安全ボディ/4WD/アイドリングストップ/ターボ/シートヒーター/DVD再生/ミュージックサーバー/ミュージックプレイヤー接続可/フロントカメラ/サイドカメラ				
検査記入欄				
小A、小U				
A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損				
月 日 まで				
VM4-140578				
cm cm cm kg				