


2019 Subaru Stella G Smart Assist		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-LA150F	DISPLACEMENT 658 cc		
YEAR / REG. 2019/08	MILEAGE 185,218 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Kei		
CHASSIS NO. LA150F-2602091	DIMENSIONS (L X W X H) 340 × 148 × 163 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
INSPECTOR REPORT			
Headliner scuffs, interior odor, seat stains and burn holes			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 8月	メーカー スバル 車名 ステラ	ドア枚数 5	ボディ構造 軽四	評価点 3.5																				
車種 自家用・その他 ()	排気量 660 cc	型式 DBA-LA150F	通称 軽四	内装 A・B・C																				
車検 - - 年 / 月	燃料 ガソリン	ディーゼル ハイブリッド ()	後日送付品 (保証書・取扱説明書 等)																					
走行 185,218 km	シフト AT	登録区分 4WD																						
外装色 シルバー	カラーNo. ()	エアコン ()	新車品のみ O印 を記入																					
内装色 ()	標準定員 人	サンルーフ ()	カーシート ()	ナビ ()																				
左・右 ()	輸入 ()	ディーラー ()	走行 ()	8,780円・預託金																				
セールスポイント																								
検査記入欄		修復歴 有 ()																						
書類送付は成約後10日前後がかかります。		<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラス/キズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>			A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ/ボケ	G	ガラス/キズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ/ボケ	G	ガラス/キズ															
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済															
天張りスレ		登録No. () 月 () 日 までに名変できる方																						
ルーム内ニオイ有		名変中																						
シートシミ・コゲ穴		車検 LA150F-2602091																						
FW ()	トビ ()	ワレ ()	外装 ()	小 ()																				
内装 ()	シミ ()	ヤブレ ()	コゲ ()	コゲ穴 ()																				
オーディオ穴 ()	エアロ ()	シリアル No.	重量 cm	高さ cm																				
最大積載量 kg																								