

2019 Suzuki Alto 5D F		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-HA36S	DISPLACEMENT 658 cc		
YEAR / REG. 2019/08	MILEAGE 94,311 km		
DOORS 5	SEATS 4		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Kei		
CHASSIS NO. HA36S-525725	DIMENSIONS (L X W X H) 340 × 148 × 148 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Minor scratches (A) and lines (A) on the body. Partial peeling (P) on the roof. Interior has stains (A) and seat repair marks. Front bumper has cracks.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 / 8月	メーカー スズキ 車名 アルト	ドア枚数 5	ボディ形状 軽四	評価点 4																																																												
グレード F 4WD・シートヒーター・社外アルミ・社外フォグ	駆動区分 2WD 4WD																																																															
車種 自家用・その他 ()	排気量 660 CC	型式 DBA-HA36S	通称 軽四	内装 A・B																																																												
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼル	検定通り品 (保証書・取扱説明書 等)																																																													
走行 94,311 km	シフト インパネ	AT																																																														
外装色 ブラック	カラーNo. ZJ3	エアコン	装備品のみ O印 を記入																																																													
()	内装色	4人																																																														
左・右 左・右	輸入区分 ディーラー・並行	7,500円・預託金	エアロック	ナビ																																																												
セールポイント CD/横滑り防止装置 (ESC) /運転席エアバック/盗難防止システム/キーレスエントリー/ABS/助手席エアバック/衝突安全ボディ/4WD/シートヒーター																																																																
検査記入欄 ボディ小A、線A ルーフPアセ部分的 内装シミ、A、シート補修跡有 Fバンパーワレあり		<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ/ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>Q</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> <tr> <td colspan="10">登録No. 月 日 までにも名実できる方</td> </tr> <tr> <td colspan="10">車体番号 HA36S-525725</td> </tr> <tr> <td colspan="10">FW トピ石 傷A フレ 外装 小 A・U A・曲 A・フレ</td> </tr> <tr> <td colspan="10">内装 ヨゴレ シミ ヤブレ コゲ コゲ穴 オーディオ穴 スレ</td> </tr> </table>			A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済	登録No. 月 日 までにも名実できる方										車体番号 HA36S-525725										FW トピ石 傷A フレ 外装 小 A・U A・曲 A・フレ										内装 ヨゴレ シミ ヤブレ コゲ コゲ穴 オーディオ穴 スレ									
A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラスキズ																																																							
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																																																							
登録No. 月 日 までにも名実できる方																																																																
車体番号 HA36S-525725																																																																
FW トピ石 傷A フレ 外装 小 A・U A・曲 A・フレ																																																																
内装 ヨゴレ シミ ヤブレ コゲ コゲ穴 オーディオ穴 スレ																																																																