


2019 Suzuki Alto 5D L		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-HA36S	DISPLACEMENT 658 cc		
YEAR / REG. 2019/06	MILEAGE 24,174 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR White		
BODY TYPE Kei			
CHASSIS NO. HA36S-518631	DIMENSIONS (L X W X H) 340 × 148 × 148 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
D-mirror A, seat dirty/scratched, headliner dirty. Steering wheel grip scratched, floor carpet dirty. Rough P mark erased from signboard.			

ORIGINAL JAPANESE AUCTION SHEET

R1 / 6月		メーカー スズキ		ドア枚数 5	ボディ形状 軽四	評価点 3.5																				
車名 アルト		グレード L		駆動区分 2WD 4WD																						
車種 自家用・その他 ()	排気量 650	型式 DBA-HA36S	通称 型式	内装 A・B・C																						
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼル	検印選り込み (保証書・取扱説明書 等)																							
走行 24,174 km	シフト AT																									
外装色 ホワイト	カラーNo. 26U	エアコン	装備品のみ O印 を記入																							
()	内装色	4人	AW サンルーフ 革シート																							
左・右 左・右	ディーラー・並行	7,500円・預託金	エレクトロニック	ABS	ナビ	TV キーレス																				
セールスポイント デュアルセンサーブレーキサポート、車線逸脱警報、アイドリングストップ、ESC、AEB																										
検査記入欄 DミラーA、シートヨゴレスレ、天張りヨゴレ ハンドルグリップスレ、フロアーカーペットヨゴレ カンパン消しP粗			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみサレ</td><td>B</td><td>キズ・ヘコミ</td><td>P</td><td>色あせ・ボケ</td><td>Q</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>				A	キズ	U	ヘコみサレ	B	キズ・ヘコミ	P	色あせ・ボケ	Q	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみサレ	B	キズ・ヘコミ	P	色あせ・ボケ	Q	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																	
登録No. HA36S-518631			名義中 月 日 までにも名義できる方																							
車検 2021年 6月 10日			車検 2021年 6月 10日																							
内装 ヨゴレ			外装 ヨゴレ																							
シス			ヤブレ																							
コガ			コガ																							
オーディオ			オーディオ																							
重量 1,000 kg			重量 1,000 kg																							