

2019 Suzuki Alto 5D L		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-HA36S	DISPLACEMENT 658 cc		
YEAR / REG. 2019/08	MILEAGE 102,522 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Kei		
CHASSIS NO. HA36S-524855	DIMENSIONS (L X W X H) 340 × 148 × 148 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Document delivery takes about 10 days after contract. Steering wheel worn, headliner yellowed, interior dirty, rust in engine compartment, inner pillar damage, undercarriage corrosion (C2).			

ORIGINAL JAPANESE AUCTION SHEET

R1 / 8月		メーカー スズキ		ドア枚数 5	ボディ形状 軽四	評価点 3.5																				
車名 アルト		グレード L		駆動方式 2WD	4WD																					
車種 自家用・その他 ()	積気量 660 CC	型式 DBA-HA36S	通称形式	内装 A・B	C																					
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼル	検出通り品 (保証書・取扱説明書 等)																							
走行 102,522 マイル		シフト AT																								
外装色 ホワイト	カラーNo. ()	エアコン	装備品のみ O印 を記入																							
()	内装色 ()	安全装置	人	PS	FS	AS																				
ハンドレ 左・右	輸入区分	ディーラー・並行	7,500円・預託制	エアバック	ABS	ナビ																				
セールスポイント																										
検査記入欄			修復歴 有・無																							
納期送付は成約後10日前後からかります。 ハンドルバグ 天幕りキバミ 室内汚れ エンジンルーム内サビ ビラーインナーBU 下回りC2			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみサレ</td><td>B</td><td>キズ・ヘコミ</td><td>P</td><td>色あせ・ボケ</td><td>Q</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>				A	キズ	U	ヘコみサレ	B	キズ・ヘコミ	P	色あせ・ボケ	Q	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみサレ	B	キズ・ヘコミ	P	色あせ・ボケ	Q	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																	
登録No. 月 日			名義中																							
車体番号 HA36S-524855																										
FW	トビ	フレ	外装	小	ホイル	エアロ																				
内装	シス	ヤブレ	コグ	コグ穴	オーディオ穴	シリアル No.																				
長さ	幅	高さ	最大積載量																							
cm	cm	cm	Kg																							