

2019 Suzuki Alto Van VP		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
HA36V	658 cc		
YEAR / REG.	MILEAGE		
2019/05	56,000 km		
DOORS	SEATS		
5	4		
TRANSMISSION	FUEL		
AT	Petrol		
STEERING	EXTERIOR COLOR		
Right	White		
BODY TYPE			
Kei			
CHASSIS NO.	DIMENSIONS (L X W X H)		
HA36V-141692	340 × 148 × 148 cm		
SALES POINTS			
Pre-Collision Braking			
INSPECTOR REPORT			
Interior scratches and dirt, seat scuffs and wrinkles, exterior minor scratches and light scratches, minor rust on underbody.			

初年度登録		メーカー		スズキ		ドア数		5		ボディ形状		軽四		評価点	
R1 / 5月		車名		アルト		グレード		V P		駆動方式		2WD 4WD		4.5	
		車種		軽乗用・その他 ()		排気量		660 CC		型式		HA36V			
車検		- - 年		月		日		燃料		ガソリン		ディーゼル		後日送り品 (保証書・取扱説明書 等)	
走行		口内にマークを記入(※交換・改造は不可)		シフト		ハイブリッド		()							
外装色		カラーNo.		エアコン		()		AAG・WAG・()							
スペリアホワイト		()		内装色		標準足量		4人						装飾品のみ O印 を記入	
()															
ハンドル		左・右		ディーラー		並行		リサイクル料		7,410円		買取額		エブリック	
														PW AW サンルーフ 革シート	
														ナビ TV キーレス	

セールスポイント

横滑り防止装置 (ESC) / 運転席エアバック/ 盗難防止システム/ キーレスエントリー / A B S / 助手席エアバック / 衝突被害軽減ブレーキ/ 衝突安全ボディ

検査記入欄

内装キズ、汚れ
シートスレ、シワ
外装小キズ、薄キズ
下廻り小

修復歴

有 ()

A	型式	U	へコボサレ	B	キズ・へコボ	P	色退セツボ	G	ガラスキズ
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
表紙No.	月 日 まで(に)名義できる方								
車体番号	HA36V-141692								

FW	()	傷A	フレ	外装	小	ホイール	エアロ	シリアル	
					()・()	A	曲	A	フレ
内装	()	シシ	ヤブレ	コゴ	コガタ	オーデイオ	()	変換	名義中