

2019 Toyota Corolla Axio 1.5X ECVT		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-NRE161	DISPLACEMENT 1,496 cc		
YEAR / REG. 2019/08	MILEAGE 184,499 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Sedan		
CHASSIS NO. NRE161-0081441	DIMENSIONS (L X W X H) 440 × 169 × 146 cm		
SALES POINTS			
Pre-Collision Braking			
INSPECTOR REPORT			
Seat wear, headliner dirty, interior dirty/scratches/scuffs, engine C.			

ORIGINAL JAPANESE AUCTION SHEET

車種名	カローラ アクシオ	グレード	1.5X ECVT	評価点
初年度登録	2019年08月	燃料	ガソリン	3.5
認定型式	DBA-NRE161	シフト	AT	内装評価点
車台番号	NRE161-0081441	走行距離	184,499km	C
排気量	1,500cc	系統色	銀	
駆動	2WD	車検	車検期限 年 月	
リサイクル料	9,470円	車歴	自家用	
		乗車定員	5	
		ドア枚数	-	

コアサポート

ロアサポート

バンパーホースメント

サイドメンバー突起部

クロスメンバー

サイドメンバー

インサイドパネル

フロア (キャブ床)

ピラーインナー

A

B

ダッシュパネル

センターフロア

ルーフパネル

サイドシルインナー

フロアサイドメンバー

セットバック(キャブ背)

ピラーインナー

C

D

トランクフロア

インサイドパネル

サイドメンバー

クロスメンバー

バックパネル

バンパーホースメント

下回り

C2

特殊

フォグ

ヘッドライト

ウィンカー

アウターミラー

サイドウィンドー

フロント

リア

荷室

テールランプ

バンパーランプ

A2

A2

G

B2

U2

A2

フォグ

ヘッドライト

ウィンカー

アウターミラー

サイドウィンドー

フロント

リア

荷室

テールランプ

バンパーランプ

書類送付は成約後10日前後からります

シートヘタリ 天張り汚れ 車内汚れ・スレ・キズ エンジンC

U、D：押され/曲がり/歪み