


2019 Toyota HIACE VAN DX		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CBF-TRH200V	DISPLACEMENT 1,998 cc		
YEAR / REG. 2019/06	MILEAGE 21,006 km		
DOORS 5	SEATS 3		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Minivan		
CHASSIS NO. TRH200-0302257	DIMENSIONS (L X W X H) 469 × 169 × 198 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Trunk floor has minor unevenness. Cargo area has scratches and minor unevenness. Console has large scratches and glue residue. Corner panel has distortion.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 6月	メーカー トヨタ	ドア枚数 5	ボディ形状 バン	評価点 R																				
車名 ハイエースバン DX	駆動方式 2WD 4WD																							
車種 自家用・その他 ()	積載量 1990 kg	型式 CBF-TRH200V	通称 型式	内装 A・B・C																				
車検 9年6月	燃料 ガソリン	ディーゼル	後付選り品 (保証書・取扱説明書 等)																					
走行 21,006 km	シフト インパネ	AT																						
外装色 シルバー	カラーNo. 1E7	エアコン	装備品のみ O印 を記入																					
()	内装色	3人	AW サンルーフ 革シート																					
左・右 左・右	ディーラー・並行	9,550円・預託金	エブリック	キーレス																				
セールスポイント セーフティセンス ナビ TV ビルトインETC																								
検査記入欄 トランクフロアU 荷室AU コンソールA大・のり跡 コーナーパネルW		<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ/ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>Q</td><td>ガラス/キズ</td></tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td></tr> </table>			A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラス/キズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラス/キズ															
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済															
		登録No. 月 日 までにも変更できる方																						
		車体番号 TRH200-0302257																						
FW	トビ石	フレ	外装	小	ホイール	エアロ																		
内装	シス	ヤブレ	コガ	コガ穴	オーディオ穴	スレ	長さ	幅	高さ	最大積載量														
							469 cm	169 cm	198 cm	1250 kg														