

2019 Toyota Hiace Wagon DX		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CBA-TRH214W	DISPLACEMENT 2,693 cc		
YEAR / REG. 2019/08	MILEAGE 23,615 km		
DOORS 4	SEATS 10		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Station Wagon		
CHASSIS NO. TRH214-0057538	DIMENSIONS (L X W X H) 484 × 188 × 210 cm		
SALES POINTS			
Back Camera		Navigation System	
INSPECTOR REPORT			
Exterior wrapped, Rear panel minor dent, Cargo area minor scratch			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 8月	メーカー トヨタ	ドア枚数 4	ボディ形状 ステーションワゴン	評価点 4																				
車種 ハイエースワゴン	グレード DX	駆動方式 2WD	4WD																					
車体 自家用・その他 ()	排気量 2690 cc	型式 CBA-TRH214W	通称 型式	内装 A・⑨・C																				
車検 - - 年 月 日	燃料 ハイブリッド	ディーゼル ()	後日送り品 (保証書・取扱説明書 等)																					
走行 23,615 km	インパネ	AT																						
外装色 シルバー	カラーNo. (1E7)	エアコン AG・AAG・⑨AG・()	新着品のみ ○印 を記入																					
内装色 ()	乗車定員 10人	⑨	AW	サンルーフ																				
ハンドル 左・()	輸入 区分	ディーラー ・ 並行	ナビ	TV																				
セーリングポイント セーフティセンス パワースライドドア ナビ ETC ドラレコ キーレス LEDヘッドライト																								
検査記入欄 外装ラッピング加工 RパネルU 荷室A		<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ/ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>			A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	G	ガラスキズ															
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済															
登録No. TRH214-0057538		名義中 月 日 までに名義できる方																						
シリアル No.		車検 484 cm																						
内装 ⑨		最大積載量 Kg																						