

2019 Toyota Hiace Wagon DX		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE CBA-TRH214W	DISPLACEMENT 2,693 cc		
YEAR / REG. 2019/07	MILEAGE 7,625 km		
DOORS 4	SEATS 10		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Station Wagon		
CHASSIS NO. TRH214-0057488	DIMENSIONS (L X W X H) 484 × 188 × 210 cm		
INSPECTOR REPORT			
R panel minor unevenness, exterior adhesive residue, underbody paint damage, dashboard screw holes.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 / 7月		メーカー トヨタ		ドア枚数 4	ボディ形状 ステーションワゴン	評価点 4																				
車名 ハイエースワゴン DX		グレード 2WD		駆動区分 4WD																						
車歴 自用・その他 ()	排気量 2690	型式 CBA-TRH214W	通称 型式	内装 A・B・C																						
車検 - 年 - 月 / 日	燃料 ガソリン	ディーゼル	後日送り品 (保証書・取付説明書 等)																							
走行 口内にマークを記入 (〇: 交換 〇: 点検 〇: 点検 〇: 点検)	シフト インパネ	AT	Sキー																							
外装色 シルバー	カラーNo. (1E7)	エアコン AG・AAG・AG・()	新備品のみ 〇印 を記入																							
()	色車検は口内に 「色検」と記入	乗車定員 10 人	PS	PS	AW	サンルーフ																				
ハンド 左・右	輸入 区分	ディーラー 並行	リサイクル料 13,180 円	預託金 エディック	ABS	ナビ																				
セールスポイント セーフティセンス キーレス																										
検査記入欄 RパネルU 外装のり跡 下回りP ダッシュピス穴			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ・凹み</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・剥け</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換所</td> </tr> </table>				A	キズ	U	ヘコみ・凹み	B	キズ・ヘコみ	P	色あせ・剥け	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所
A	キズ	U	ヘコみ・凹み	B	キズ・ヘコみ	P	色あせ・剥け	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所																	
登録No.			名義中																							
月 日			までに名義できる方																							
車体 番号			TRH214-0057488																							
シリアル No.																										
PW	トヨタ	備A	フレ	外装	小 A・G	ホイール A・曲	エアロ A・フレ																			
内装	ヨコ	シミ	ヤブレ	コゲ	コゲ穴	オーディ穴	シ																			
長さ	484 cm	幅	188 cm	高さ	210 cm	最大積載量 Kg																				