

2019 Toyota Sienta G 4WD		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-NCP175G	DISPLACEMENT 1,496 cc		
YEAR / REG. 2019/11	MILEAGE 96,750 km		
DOORS 5	SEATS 6		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Minivan		
CHASSIS NO. NCP175-7036362	DIMENSIONS (L X W X H) 426 × 170 × 170 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking		Power Sliding Doors (Both Sides) (Both... Navigation System	
INSPECTOR REPORT			
Light scratches on exterior, interior trim damage, aftermarket aluminum wheels.			

ORIGINAL JAPANESE AUCTION SHEET

R1 / 11月		トヨタ		ドア枚数 5	ボディ形状 ミニバン/ワンボックス	駆動方式 2WD	4WD	4																				
シエンタ		G 4WD																										
車種 自家用・その他 ()	排気量 1500 cc	型式 DBA-NCP175G	通称 型式	内装 A・③・C																								
車検 -年-月-日	燃料 ④	ディーゼル	後付選り品 (保証書・取扱説明書 等)																									
走行 96,750 km	インパネ	AT																										
外装色 ブラック	カラーNo. (209)	エアコン AG・⑥AG・WAG・()	装備品のみ O印 を記入																									
内装色 ()	乗車定員 6 人	⑤	⑦	⑧	⑨	サンルーフ	革シート																					
左・⑧	輸入 区分	ディーラー	走行	リサイクル料	10,360円	⑩	⑪	⑫																				
セールスポイント																												
トヨタセーフティセンス、パノラミックビューモニター、スマートキー、外AW				修復歴 有・⑬																								
検査記入欄				<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/凹み</td><td>B</td><td>キズ/ヘコみ</td><td>P</td><td>色あせ/剥け</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換部</td><td>XX</td><td>交換済</td> </tr> </table>					A	キズ	U	ヘコみ/凹み	B	キズ/ヘコみ	P	色あせ/剥け	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換部	XX	交換済
A	キズ	U	ヘコみ/凹み	B	キズ/ヘコみ	P	色あせ/剥け	G	ガラスキズ																			
W	補修跡	S	サビ	C	腐食	X	交換部	XX	交換済																			
外装うすい線キズ、室内内張傷、社外アルミホイール				登録No. 月 日 までに変更できる方																								
				車体番号 NCP 175-7036362																								
FW ⑭				シリアル No.																								
内装 ⑮				重量 cm 最大積重量 kg																								