


2019 Toyota Sienta Hybrid Hybrid Funbase G		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE 6AA-NHP170G	DISPLACEMENT 1,496 cc		
YEAR / REG. 2019/01	MILEAGE 45,703 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Brown	BODY TYPE Minivan		
CHASSIS NO. NHP170-7153610	DIMENSIONS (L X W X H) 426 × 170 × 168 cm		
SALES POINTS			
Power Sliding Doors (Both Sides) (Both... Cruise Control		Pre-Collision Braking Navigation System	
INSPECTOR REPORT			
Exterior has minor scratches and dents. Interior has stains and scratches.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録	車 名		ドア・開状態		グレード		駆動		総合評価点
31 1	シエンタ		5	ハイブリッド* ファンベースG		4.5			
型 式		排気量	燃料	車 種	定員(最大)	積載量(最大)	輸 入 車		
6AA	NHP170G	1,500 _{CC}	ガソリン	自家用	名	kg	年式月日		
ミッション	エアコン	カラー	外 装 色		保 険		保証書	取扱	内装評価
IAT	AAC	2SG	ベージュ2		PS	PW	I7B	ABS	有
走行距離		車 検	登録ナンバー		注力・装備		車台番号		預託金
45,703 _{km}		10 年 1 月	尾張小牧503ふ3362				NHP170-7153610		10,360 円
セールスポイント			特記事項・不具合箇所						
車検R10年1月まで ワイドナビ・地デジTV トヨタセーフティセンス クルーズコントロール 両側パワースライドドア			外装 小キズ 小凹 内装 ヨゴレ キズ						
注 意 事 項									
スマートキー・ETC									
シート/ステアリングヒーター									
保証書、取扱、Sキー 後日									
									
			A (キズ)・H (ヘコミ)・B (キズを伴うヘコミ)・W (補修跡)・P (変造箇所) D (錆)・C (腐食)・X (交換済み)・X (要交換)・G (ガラス破損等)						

A (キズ)・U (ヘコミ)・B (キズを伴うヘコミ)・W (傷痕跡)・P (変色箇所)
S (錆)・C (腐食)・XX (交換済み)・X (要交換)・G (ガラス破損等)