


2019 Toyota Succeed Van Hybrid UL		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 6AE-NHP160V	DISPLACEMENT 1,496 cc		
YEAR / REG. 2019/07	MILEAGE 142,708 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Hatchback		
CHASSIS NO. NHP160-0010076	DIMENSIONS (L X W X H) 425 × 169 × 153 cm		
SALES POINTS			
Back Camera		Navigation System	
INSPECTOR REPORT			
Minor dents/unevenness in cargo area.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 / 7月		メーカー トヨタ		ドア枚数 4	ボディ形状 コンパクト/ハッチバック	評価点 4																				
車名 サクシード		グレード UL		駆動方式 4WD																						
車種 自家用・その他 ()	排気量 1500 cc	型式 6AE-NHP160V	通称 型式	内装 A・B・C																						
車検 - - 年 / 月	燃料 ガソリン	ディーゼル	後日送付品 (保証書・取扱説明書 等)																							
走行 142,708 km	シフト AT																									
外装色 シルバー	カラーNo. ()	エアコン	新着品のみ O印 を記入																							
内装色 ()	標準定員 人	PS	PW	AW	サンルーフ	革シート																				
ハンドル 左・右	輸入 区分	ディーラー	並行	7,440円	ナビ付	TV																				
セールスポイント																										
検査記入欄			修復歴 有・無																							
書類送付は成約後10日前後がかかります。			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>				A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ/ボケ	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																	
荷室 A U			登録No. _____ 月 _____ 日 までに名義できる方																							
			車検番号 NHP 160-0010076																							
FW	トビ	ワレ	外装	小	オイル	エアロ	シリアル No.																			
内装	シミ	ヤブレ	コガ	コガ穴	オーディオ穴	車検	最大積載量 kg																			