


2019 Toyota Succeed Van UL-X		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBE-NCP160V	DISPLACEMENT 1,496 cc		
YEAR / REG. 2019/08	MILEAGE 217,815 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Minivan		
CHASSIS NO. NCP160-0121686	DIMENSIONS (L X W X H) 425 × 169 × 153 cm		
SALES POINTS			
Alloy Wheels		Back Camera	
INSPECTOR REPORT			
Headliner scuffs, interior dirt, steering wheel scuffs, seat stains/burn holes, outer mirror scratches.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 8月	メーカー トヨタ 車名 サクシード	ドア枚数 5 グレード UL-X	ボディ形状 バン 駆動区分 4WD	評価点 3.5																				
車種 自家用・その他 ()	排気量 1500 cc	型式 DBE-NCP160V	通称 型式	内装 A・B・C																				
車検 - - 年 / 月	燃料 ガソリン	ディーゼル	後日送付品 (保証書・取扱説明書 等)																					
走行 217,815 km	シフト AT																							
外装色 シルバー	カラーNo. ()	エアコン	新車品のみ O印 を記入																					
内装色 ()	乗車定員 人	PS	サンルーフ	革シート																				
ハンド 左・右	輸入 区分	ディーラー	走行 7,440 km	ナビ																				
セールスポイント																								
検査記入欄		修復歴 有 ()																						
書類送付は成約後10日前後がかります。		<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ/ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラス/キズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>			A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	G	ガラス/キズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	G	ガラス/キズ															
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済															
天板リズレ		登録No. 月 日 までに名義できる方																						
ルーム内汚れ		名義中																						
ハンドルズレ		車検 NCP160-0121686																						
シートシミ・コゲ穴		車検 cm																						
アウターミラーズ		車検 cm																						
FW		車検 cm																						
内装		車検 cm																						