

2019 Toyota TANK Custom G		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-M900A	996 cc		
YEAR / REG.	MILEAGE		
2019/04	85,200 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Pearl White	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
M900A-0313841	373 × 167 × 174 cm		
SALES POINTS			
Alloy Wheels		Power Sliding Doors (Both Sides) (Both...	
Pre-Collision Braking		Cruise Control	
Back Camera		Navigation System	
INSPECTOR REPORT			

新年度登録 H31 / 4月	メーカー トヨタ	ドア枚数 5	原付/原付 コンパクト/ハッチバック	評価点 4.5																																																		
車種 自家用 ・ その他 (	排気量 1000	型式 DBA-M900A	燃費 2WD 4WD	内装 A ・ B ・ C																																																		
車検 - - 年 / 月 / 日 (印内にマークを記入 (●: 交換) ●: 点検)	燃料 ガソリン ハイブリッド (	ディーゼル (	検日渡り品 (保証書 ・ 取扱説明書 等)																																																			
走行 85,200 km (印内にマークを記入 (●: 交換) ●: 点検)	シフト CVT	装備品のみ O印 を記入																																																				
外装色 グラックスメタリックパールホワイトIII カラーNo.	エアコン (●: A/C ・ WAG ・ (	車検定員 5 人																																																				
(	車検定員 5 人	(●: A/C ・ WAG ・ (	サンプル	車シート																																																		
ハンド 左 ・ 右	ディーラー ・ 走行	サイズ/カラー 9,130 円 ・ 預託金	エア/バック	ミニ																																																		
セールスポイント																																																						
社外9インチナビ/スマートアシスト(トヨタ・ダイハツ)/両側電動スライドドア/シートヒーター 前席/ヘッドランプ LED/TC/BD付ABS/横滑り防止装置																																																						
検査記入欄																																																						
<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみ/サレ</td><td>B</td><td>キズ/へこみ</td><td>P</td><td>色あせ/ボヤ</td><td>Q</td><td>ガラスキズ</td></tr> <tr> <td>W</td><td>修繕跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td></tr> <tr> <td colspan="10"> 登録地 月 日 </td></tr> <tr> <td colspan="10"> 車体番号 M900A-0313841 </td></tr> <tr> <td colspan="10"> シリアル No. 車種 年式 最大積載量 </td></tr> </table>					A	キズ	U	へこみ/サレ	B	キズ/へこみ	P	色あせ/ボヤ	Q	ガラスキズ	W	修繕跡	S	サビ	C	腐食	X	交換済	XX	交換済	登録地 月 日										車体番号 M900A-0313841										シリアル No. 車種 年式 最大積載量									
A	キズ	U	へこみ/サレ	B	キズ/へこみ	P	色あせ/ボヤ	Q	ガラスキズ																																													
W	修繕跡	S	サビ	C	腐食	X	交換済	XX	交換済																																													
登録地 月 日																																																						
車体番号 M900A-0313841																																																						
シリアル No. 車種 年式 最大積載量																																																						