


2019 Toyota TANK G		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-M900A	996 cc		
YEAR / REG.	MILEAGE		
2019/03	19,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Red	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
M900A-0304574	370 × 167 × 174 cm		
SALES POINTS			
Power Sliding Doors (Both Sides) (Both... Cruise Control Navigation System		Pre-Collision Braking Back Camera	
INSPECTOR REPORT			
Interior scuffs			

新年度登録		メーカー トヨタ		ドア数 5		ボディ種別 コンパクトハッチバック		特価点 A ⑤・C		
H31 / 3月	タンク			車名	グレード G	駆動方式 2WD 4WD	9.5			
車種 自家用・その他（ ）	排気量 1000 CC	型式 DBA-M900A	通称形式	内装	A ⑤・C					
年次 - - 年 月 日	燃料 ガソリン	ディーゼル	償得り品（保証書・取扱説明書等）							
走行 口角にマーク付与記入(※交換) ←(※区分) (※不備) 方 子 円 分 秒 19 , 000	シフト インパネ AT									
外装色 ワインレッド	カラーNo. ()	エンジン QD・AGD・WAC・()	装備内容 5人			価格表示のみ O印 を記入				
左・前 輸入 区分	ディーラー	運行	リサイクル料	9,130円	買取額	EPA値	ABS	AW	サドルーフ	革シート
セールスポイント						修復歴 有 ()				
キーレスエントリー/運転席エアバック/C/Dナビ/衝突被害軽減ブレーキTC/Aイドリングストップ/スマートキー/オートクルーズコントロール/バックカメラ										
検査記入欄						A キズ U ヘッドライト B キズへくず P 自動センサー G ガラスキズ W 傷跡 S サビ C 腐食 X 交換機 XX 交換済				
内装スレ						査定 月 日 家で各表で定める				
PW トボ石	傷A	ワレ	外装	小 ①・②	ホイール A・B	エプロン シリアル No.	M900A-0304574	最大積載重量		
内装	ヨゴレ	シミ	ヤブレ	コゲ	コグス	オーデイオS	③	最高時速	Cm	Cm