

2019 Volkswagen VW Golf 5HB TSI Comfortline Tech Edition		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-AUCJZ	DISPLACEMENT 1,197 cc		
YEAR / REG. 2019/03	MILEAGE 27,754 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Hatchback		
CHASSIS NO. WVWZZZAUZKP025689	DIMENSIONS (L X W X H) 427 × 180 × 148 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control Navigation System		Pre-Collision Braking Back Camera	
INSPECTOR REPORT			
Minor scuffs on seats, minor wear on cargo area lining (grade A), minor scuffs on steering wheel, minor stone chip on front glass.			

ORIGINAL JAPANESE AUCTION SHEET

H31/3月		メーカー フォルクスワーゲン		ドア数 5		ボディ形状 コンパクト/ハッチバック		評価点 5	
車種 自家用・その他()		排気量 1200 cc		型式 DBA-AUCJZ		燃料 ガソリン		駆動方式 FF	
年 27		月 7		日 5		グレード TSIコンフォートライン テックエディション		4WD	
走行 27,754 km		シフト フロア		AT		後部座席 ()		オプション ()	
外装色 パールホワイト		カラーNo. A		エンジン 1.8 TSI		安全装備 ()		装備品のみ O印 を記入	
走行 14,760 km		走行 14,760 km		走行 14,760 km		走行 14,760 km		走行 14,760 km	
セールスポイント Discover Pro SSDナビ、バックカメラ、フルセグTV/ACC/LEDライトETC/純正17AW		検査記入欄 AIS 査定評価 シートずれ(小) 荷室内張りA(小) ハンドルずれ(小) Fガラス飛び石(小)		修復歴 有 ()		A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損		名義中 月 日 まで名義できる方	
内装 パールホワイト		外装 パールホワイト		小 A・U		中 A・U		大 A・U	
内装 パールホワイト		外装 パールホワイト		小 A・U		中 A・U		大 A・U	