

2019 Volkswagen VW Golf GTI Performance		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
AUDLB	1,984 cc		
YEAR / REG.	MILEAGE		
2019/04	37,200 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Blue	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WVWZZZAUZKW098393	428 × 180 × 147 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Adaptive Cruise Control		Back Camera	
Navigation System			
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H31/4月	メーカー フォルクスワーゲン 車名 ゴルフGTI	ドア数 5	ボディ形状 コンパクト/ハッチバック	評価点 5
車種 自家用・その他()	排気量 2000 CC	型式 AUDLB	選定 型式	内装 A・B・C
車検 10年4月	抹消 燃料 ハイブリッド	ディーゼル	後付選用品(保証書・取扱説明書等)	
走行 37,200 km	シフト フロア 7 AT			
外装色 ダークアイアンブルーメタリック	カラーNo. ()	エアコン A・AAG・WAG・()	装備品のみ O印 を記入	
内装色 ()	乗車定員 5人	サンルーフ 革シート		
左・右 左・右	輸入 国産	走行 15,370円	燃料 エコ	その他 A・B・C
セールスポイント CD/バックカメラ/横滑り防止装置(ESC)/運転席エアバック/衝突防止システム/スマートキー/キーレスエントリー/A B S /助手席エアバック/サイドエアバック/メモリーナビゲーション/フルセグTV/衝突被害軽減ブレーキ/衝突安全全ボディ/アイドリングストップ/ターボ/DVD再生/ミュージックサーバー/ミュージックプレイヤー接続可		修復歴 有・無		
検査記入欄		A キズ U ヘッドライト B キズヘッド P 色あせ/ボケ Q ガラスキズ W 補修跡 S ヤビ C 腐食 X 交換済 YX 交換済 登録No. 月 日 名変中 車体番号 WVWZZZAUZKW098393 FW トボ石 傷A フレ 外装 小 A・U ホイル A・曲 A・フレ エアロ 内装 ヨゴレ シシ ヤブレ コガ コガ穴 オーディオ穴 スレ		
		取崩 長さ cm 幅 cm 高さ cm 最大積載量 Kg		