

2019 Volkswagen VW Polo 5HB TSI Highline		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
AWCHZ	999 cc		
YEAR / REG.	MILEAGE		
2019/05	18,400 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Red	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WVWZZZAWZKU069850	406 × 175 × 145 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Adaptive Cruise Control		Back Camera	
Navigation System			
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 / 5月	メーカー フォルクスワーゲン	ドア数 5	ボディ形状 コンパクト/ハッチバック	評価点 4.5
車名 ポロ	グレード TSIハイライン	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 1000 CC	型式 AWCHZ	選装 型式	内装 A・B・C
車検 - - 年 - 月	燃料 ガソリン	ディーゼル	後付選用品 (保証書・取扱説明書 等)	
走行 18,400 km	シフト フロア 7 AT			
外装色 フラッシュレッド	カラーNo.	エアコン	装備品のみのO印を記入	
()	内装色	QW・AAG・WAG・()		
左・右 左・右	輸入 国産	乗車定員 5人	サンルーフ	革シート
14,040円	14,040円	14,040円	14,040円	14,040円
セールスポイント CD/バックカメラ/横滑り防止装置 (ESC) /運転席エアバック/衝突防止システム/スマートキー/キーレスエントリー/A B S /助手席エアバック/サイドエアバック/メモリーナビゲーション/フルセグTV/衝突被害軽減ブレーキ/衝突安全全ボディ/アイドリングストップ/ターボ/DVD再生/ミュージックサーバー/ミュージックプレイヤー接続可				
検査記入欄				
A キズ U ヘッドライト B キズ・ヘッ P 色あせ・ボケ Q ガラスキズ W 補修跡 S ヤビ C 腐食 X 交換済 YX 交換済 登録No. 月 日 までに名実である方 車検番号 WVWZZZAWZKU069850 FW トボ石 傷A フレ 外装 小 A・U ホイル A・曲 A・フレ エアロ 内装 ヨゴレ シシ ヤブレ コガ コガ穴 オーディオ穴 スレ				
長さ cm 高さ cm 最大積載量 Kg				