

2019 VOLVO VOLVO V60 T5 Momentum		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-ZB420	1,968 cc		
YEAR / REG.	MILEAGE		
2019/10	41,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
White	Station Wagon		
CHASSIS NO.	DIMENSIONS (L X W X H)		
YV1ZW10MDK2030401	476 × 185 × 144 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Pre-Collision Braking		Adaptive Cruise Control	
Parking Assist (Auto Steering)		Back Camera	
Navigation System		High Performance Audio System (170W,...	
INSPECTOR REPORT			

年式変更欄		メーカー		型式検査		型式検出		評価点	
R1 / 10月		ボルボ		5		ステーションワゴン			
		V 6 0		T5 モメンタム		2WD 4WD		5	
車種 自家用 ・ その他 ()		排気量 2000 CC		型式 DBA-ZB420		登録形式		内装 A B C	
車体 - - 年 月 / 日		製 造 年 月		ディーゼル		後付部品名 (他社品・取付け済等)			
走行 100kmに消費する燃料 (リッター) 41.000		シフト ハーフシフト		保証書・取扱説明書・スペアキー後日送付					
外装色 クリスタルホワイトパール		カラーNo.		エディション		後付品のみの O印 を記入			
()		内装色		オプション		PS PW AW サンルーフ モーシート			
左 ()		右 ()		走行		ABS ナビ TV キーレス			
価格 24,360円		消費税 2,436円		総額 26,796円					
セールスポイント									
ブロード内装・ディスプレイオーディオ・ドラレコ・Pアシスト・MOMOホイール・バックカメラ・Pシート・シートヒーター・地ナビ・Bluetooth・アプリ・衝突軽減ブレーキ・追従クルコン									
特記事項									
AISカーセンサー認定済み 5点 スペアキー有り									
検査記入欄									
修復歴 有 ()									
A	キズ	U	ヘコみ凹み	B	キズ+ヘコみ	P	色あせ・汚れ	G	ガラス割れ
W	補修跡	S	サビ	C	腐食	X	交換部	XX	交換済
検査結果									名義人
月 日									まで(任意)
車体番号 YV1ZW10MDKZ030401									
FW	トビ石	傷A	フレ	外装	小	ホイル	エアロ	シリアル No.	
内装	ゴロン	シミ	ヤブレ	コガ	コガ穴	オーディオ	()	車庫	