


2020 BMW BMW 3series Touring 320d xDrive Touring M Sport		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 6L20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2020/02	MILEAGE 74,090 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE Station Wagon		
CHASSIS NO. WBA6L72020FH46826	DIMENSIONS (L X W X H) 472 × 183 × 147 cm		
SALES POINTS			
Alloy Wheels Leather Seats Power Seats (Front) Adaptive Cruise Control Back Camera		Roof Rails Power Tailgate Pre-Collision Braking Parking Assist (Auto Steering) Navigation System	
INSPECTOR REPORT			
Front windshield stone chip, interior dirt/stain			

ORIGINAL JAPANESE AUCTION SHEET

R2 / 2月		BMW		5		ステーションワゴン		4.5	
3シリーズ		320d xDrive ツーリング Mスポーツ		2WD		4WD			
車種 自家用 ・ その他 ()		排気量 2000 cc		型式 6L20		登録区分		A・B・C	
年 月 日 9 年 2 月		燃料 ガソリン		変速機 ハンドリフト ()		後付選用品 (保証書 ・ 取扱説明書 等)			
走行 74,090 km		フロア 8 AT							
外装色 ドラバイト・グレーメタリック		カラーNo. ()		エアコン ()		新着品のみ O印 を記入			
()		内装色 ()		乗車定員 5 人		サンルーフ		X	
左・前・後 輸入車		走行 19,560 km		19,560 km		エレクトロニクス		TV	
セールスポイント BMWレーザーライト ヘッドアップディスプレイ グァーネスカレゼーシート BMWライブコックピット オートランク イノベーションPKG コンフォートPKG ハイラインPKG 19inMアロイホイール									
検査記入欄 									
修復歴 有・無 A キズ B ハコボネサレ C キズ・ヘコみ D 色あせ・サビ E ガラスキズ W 腐蝕 F サビ G 腐食 H 変色 I 交換 J 交換 K 交換 L 交換 M 交換 N 交換 O 交換 P 交換 Q 交換 R 交換 S 交換 T 交換 U 交換 V 交換 W 交換 X 交換 Y 交換 Z 交換 名義中 月 日 まで WBA6L72020FH46826 車種 年式 月 日 走行 km 最大積載量 kg									