

2020 BMW BMW X1 xDrive 18d xLine		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3DA-AD20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2020/03	MILEAGE 54,264 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE SUV		
CHASSIS NO. WBA32AD0403L89339	DIMENSIONS (L X W X H) 446 × 182 × 161 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Back Camera		Roof Rails Parking Assist (Auto Steering) Navigation System	
INSPECTOR REPORT			
Steering wheel wear, seat wear and wrinkles, minor wear on interior trim, headliner wear, minor wear in trunk, minor exterior paint wear.			

ORIGINAL JAPANESE AUCTION SHEET

R2 / 3月		BMW		5		SUV/クロカン		4																					
X 1		xDrive 18d xライン		2WD		4WD																							
車種	乗用車・その他 ()	排気量	1990 cc	型式	3DA-AD20	通称		内装	A・B・C																				
車検	9年3月 / 抹消	燃料	ガソリン	変速機	オートマ	後部追いつき () 車・取扱い明書 ()																							
走行	54,264 km	シフト	AT																										
外装色	ブラック	カラーNo.	475	エンジン	AG・AGD・WAG ()	装備品のみ O印 を記入																							
内装色	その他	乗車定員	5人	PS	○	ABS	○	サンルーフ	○																				
走行	19,180 km	リサイクル料	19,180円	エアロ	○	ナビ	○	TV	○																				
セールスポイント																													
? ドラレコ																													
? ETC																													
? シートヒーター																													
検査記入欄				<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘッドレスト</td><td>B</td><td>キズ・へこみ</td><td>P</td><td>色あせ・汚れ</td><td>Q</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>燃費</td><td>S</td><td>ナビ</td><td>C</td><td>床</td><td>X</td><td>交換部</td><td>XX</td><td>交換部</td> </tr> </table>						A	キズ	U	ヘッドレスト	B	キズ・へこみ	P	色あせ・汚れ	Q	ガラスキズ	W	燃費	S	ナビ	C	床	X	交換部	XX	交換部
A	キズ	U	ヘッドレスト	B	キズ・へこみ	P	色あせ・汚れ	Q	ガラスキズ																				
W	燃費	S	ナビ	C	床	X	交換部	XX	交換部																				
名義中				月 日 まで名義できる方																									
WBA32AD0403L89339																													
最大積載量				0 kg																									