

2020 BMW BMW X6 xDrive35d M Sport		OVERALL	
		5	
EXTERIOR		INTERIOR	
-		-	
MODEL CODE	DISPLACEMENT		
3DA-GT30	2,992 cc		
YEAR / REG.	MILEAGE		
2020/09	44,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Other	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WBAGT220209D33343	495 × 201 × 170 cm		
SALES POINTS			
Alloy Wheels		Sunroof	
Leather Seats		Power Tailgate	
Power Seats (Front)		Pre-Collision Braking	
Adaptive Cruise Control		Parking Assist (Auto Steering)	
Front Camera		Side Camera	
Back Camera		360° Camera	
Navigation System		HiFi Surround Speaker System (205W, 1...	
INSPECTOR REPORT			
While noticeable exterior scratches and dents have been neatly repaired, minor ones may still be present. The interior has some localized, noticeable stains. There is no history of major repairs or structural damage.			

[illegible]