

2020 BMW_Mini BMW Mini Clubman Cooper D Clubman Base Grade		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE 3DA-BB20M	DISPLACEMENT 1,995 cc		
YEAR / REG. 2020/12	MILEAGE 41,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Green	BODY TYPE Station Wagon		
CHASSIS NO. WMW72BB0702N06055	DIMENSIONS (L X W X H) 428 × 180 × 147 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control		Pre-Collision Braking Navigation System	
INSPECTOR REPORT			
Tire cracks, minor seat scuffs, medium wear on pillar trim, medium steering wheel scuffs, minor console wear, tinted windows, minor damage on rear bumper underside, deteriorated headlight lenses, black roof, no floor mats.			

印字位置確認	メーカー名 MINI	ドア数 5	ボディ仕様 ステーションワゴン	評価点 9.0
R2 / 12月	車名 MINI	グレード クーパー Dクラブマ ンベースグレード	駆動方式 4WD	年式 4
車種 自家用・その他()	排気量 2000	型式 CC	3DA-BB20M	内装 A・C
車検 - - 年 - - 月 / 日	燃料 ガソリン	形式 5バル	登録番号 豊田県 ()	備考 ()
走行 C区にマークが記入(金・白線) → 過去1年 何キロ	シフト オート	フロア 8 AT		
外観色 カラー名称 ブリタニッシュレーシングブルー (C3B)	エンジン QD・AAG・WAD・()	装備品のみのO印を記入		
()	内装色 黒色系	乗員定員 5人	PS	PW
左・右 デモ	輸入 区分	走行距離 17,800 km	エアロ	TV
セールスポイント				
ベッパPKG、ナビ、Bカメラ、LEDヘッド、黒ルーフ、ETC				
検査記入欄				
タイヤヒビ、シートすれ小、ピラー内張りA中、ハンドルすれ中、コンソールA小、ガラスフィルム強、R/Nパー下面A有、ヘッドライトレンズ劣化、屋根/黒、フロアマツナなし				
修復歴 有 ()				
写真撮影				
FW	キズ	U	ヘコ	ボヤレ
W	鉄粉剥離	S	サビ	C
塗装	変色	A	交換	交換
年月	日	名義		
車体番号 WWW72BB0702N06055				
内装	シロ	ヤレ	ゴケ	オチ
外装	シロ	ヤレ	ゴケ	オチ