

2020 CITROEN CITROEN C3 Shine		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
B6HN05	1,199 cc		
YEAR / REG.	MILEAGE		
2020/03	44,297 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Blue	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
VF7SXHNPLYLT504995	400 × 175 × 150 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Cruise Control		Back Camera	
Navigation System			
INSPECTOR REPORT			
No abnormalities in the frame. Mirror has rust. Right rim has partial wrinkles, scuffs, and scratches.			

青神内のゲージ鑑定/JAAA鑑定証の評価と下記記載の評価は真実となります

前年度登録 R2 / 3月	メーカー シトロエン 車名 C 3	ドア数 5 グレード シャイン	ボディ形状 コンバウトハッチバック 評価点 4
車種 自家用	ディーゼル 右	B6HND5	総重量 1200 機油 ガソリン
車検 - 年 - 月 - 日	走行距離 44,297 km	エンジン AC	燃費 17.250 km/L
外装色 ブルー I I	カラーNo. ()	リサイクル料 17,250 円・環境税 シフト 6 AT	備考欄 VF7SXHNPNP LT504995
内装色 ()	乗車定員 5 人	長さ cm	幅 cm

旅行送り状 (保証書・取扱説明書等)

装備
☒ パワーステアリング ☒ ウォーク ☒ シートヒーター
☒ ナビ ☒ TV ☒ ABS

セレクトポイント

バックカメラ/EBCブレーキ補助防止システム(S-C)・燃費改善機構(エコドライブアシスト)/A/S・防突席・バック/サイドエアバッグ衝突被害軽減ブレーキ/キーリングストップ/ターボポートクルーズコントロール

査定員記入欄

※ボデーダメージに関する注意事項
 傷は記号のみのみ
 ○ 軽傷
 △ 中傷
 × 大傷
 ※ 軽傷 ≡ A
 ※ 中傷 ≡ B
 ※ 大傷 ≡ C

W	H	L	F	R	A	S	O	D	E	T
左フロント	左リア	左側面	右側面	右フロント	右リア	後部	下部	上部	その他	不明

クオリティグレード説明

外装状態に劣るようなキズやヘコミがあった場合は絵面に補修済みですが、小さなキズやヘコミが残っている場合もあります。

内装状態に劣る汚れ等が、部分的にあります。

車体構造の確認は、停止状態で実施する予定です。