

2020 Daihatsu Boon 1.0 X		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-M700S	DISPLACEMENT 996 cc		
YEAR / REG. 2020/06	MILEAGE 6,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Hatchback		
CHASSIS NO. M700S-0027302	DIMENSIONS (L X W X H) 365 × 167 × 153 cm		
INSPECTOR REPORT			
Third-party inspection completed. Main equipment confirmed OK. Interior has dirt and scuffs, seats are dirty. Wheel caps have scratches, door mirrors have scratches. General scratches and dents.			

ORIGINAL JAPANESE AUCTION SHEET

出品票		型式指定番号	納税区分番号	シリアル番号	評価点
初年度登録 R02 6月	車名 ブーン	ドア数 5	グレード 1.0 Xスマートキー アイドリングストップ	駆動 FF	4.5
型式 5BA-M700S	排気量 1000 cc	燃料 ガソリン	軽油	内装 A	色 ⑩
車種 乗用車	年 月 5月	車歴 5	走行距離 836 km	カラーNo. 色替無	内装色 色替無
車台No. M700S	-	0027302	リサイクル 8,610	円換算済	未換算
登録No.	5	乗員数 5人	重量 1000 kg	長さ 167 cm	高さ 153 cm
輸入車のみ モデル 年式	輸入区分	ディーラー	車行	ハンドル	左
セーリングポイント スマートキー アイドリングストップ					

注意事項・不具合箇所 ★第三者機関検査済み★									
検査員記入欄：修復歴「有」の場合は修復箇所・交換箇所を記入 ★主要装備確認OK★ 内装汚れ、スレ シート汚れ ホイールCPキズ Dミラーキズ キズ、凹									
	<table border="1"> <tr> <td>ドアミラー</td> <td>キズ</td> <td>セビ</td> <td>フレ</td> </tr> <tr> <td>工具</td> <td>黒</td> <td>ジャッキ</td> <td>黒</td> </tr> </table>	ドアミラー	キズ	セビ	フレ	工具	黒	ジャッキ	黒
ドアミラー	キズ	セビ	フレ						
工具	黒	ジャッキ	黒						