

2020 Daihatsu Rocky L		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE A200S	DISPLACEMENT 996 cc		
YEAR / REG. 2020/07	MILEAGE 97,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE SUV		
CHASSIS NO. A200S-0017635	DIMENSIONS (L X W X H) 400 × 170 × 162 cm		
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
Exterior has scratches, dents, and faded resin parts. Interior has dirt and scratches. Cargo box has scratches. Interior trim has scratches and headliner has scuffs. Center pillar is pinched (AU). Wheel covers have scratches. Minor rust underneath.			

出 品 票		型式認定番号		商標(登録番号)		シリアル番号		評 価 点	
前年度登録簿		車 名		ドア数		グ レード		総重量 (kg) (公称)	
R02 年 7 月 次		ロッキー		5 日		1.0 L		4	
型式 5BA-A200S		総重量 1000		燃料 油		電 池		内 装 A B C	
車 種		改良済み		改良記入(改良事項)		車 種		純正部品 ○をつける	
年 月		車 種		レンタ		FAT		AC	
走行距離		9 万 7 千 0 0 0 km		マイル		○をつける		純正ナビ	
外装色		シャイニングホワイトパール		色別(色名) 色替無		カラーNo.		内装色	
車台No.		A200S -		0017635		リサイクル 預託金		9,260	
登録No.						内装注満		未注満	
年 月		5 年		稼働量		電 圧		電 流	
輸入車のみの モーター 形式		年		輸入区分		ディーラー		車行	
セルスインポート 衝突軽減ブレーキ		純正ナビ		CD		DVD		DVD	
注 意 事 項		不具合箇所							
検査員記入欄：修理工「有」の場合は修理箇所・交換部品を記入		外装傷凹み樹脂部色剥離		室内汚れ傷		荷箱傷		内張傷タ張りスレ	
センターピラー-挟み込み割		ホイールカバー-傷		下回りサビ小					
F.A.ミラー		ヒビ		クレ					