

2020 Daihatsu Thor Custom 1.0 Custom G		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
5BA-M900S	996 cc		
YEAR / REG.	MILEAGE		
2020/12	39,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
White	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
M900S-0076289	371 × 167 × 174 cm		
SALES POINTS			
Alloy Wheels		Power Sliding Doors (Both Sides) (Both...	
Pre-Collision Braking		Back Camera	
360° Camera		Navigation System	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R2 / 12月	メーカー ダイハツ	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 5
車名 トール	グレード 1.0 カスタムG・メーカーオプション・パノラミックビュー	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 1000 CC	型式 5BA-M900S	選装 型式	内装 A・B・C
車検 9年12月 / 抹消	燃料 ガソリン	ディーゼル	後付選用品 (62 等・ 63 等 等)	
走行 39,000 km	マイル 62,000	インパネ	CVT	
外装色 パールホワイトIII	カラーNo. ()	エアコン A・AAG・WAG・()	装備品のみの O 印 を記入	
内装色 ()	乗車定員 5 人	ドアロック A・B・C	サンルーフ	革シート
左・右 左・右	輸入 区分	ディーラー ・ 並行	ナビゲーション 9,720 円	防犯カメラ エレクトロニクス
セールスポイント ・メーカーオプション・パノラミックビューモニター・9インチプレミアムナビ・フルセグ・CD/DVD・Bluetooth・両側パワースライドドア・電動パーキングブレーキ・ブレーキホールド・クルーズコントロール				
検査記入欄 A1 修復歴 有・6 A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ Q ガラスキズ W 燃費 S ヤビ C 腐食 X 交換 Y 交換 Z 交換 登録月 月 日 年 車検 M900S-0076289 シリアル No. 内装 トゴレ シェ ヤブレ コガ コガ穴 オーディオ穴 スレ 長さ cm 幅 cm 高さ cm 最大積載量 Kg				