

2020 Honda N-VAN G Honda Sensing		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE HBD-JJ1	DISPLACEMENT 658 cc		
YEAR / REG. 2020/04	MILEAGE 82,000 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Minivan		
CHASSIS NO. JJ1-3036448	DIMENSIONS (L X W X H) 340 × 148 × 195 cm		
SALES POINTS			
Pre-Collision Braking		Adaptive Cruise Control	
INSPECTOR REPORT			
Interior and cargo area have scratches and scuffs. Minor scratches and small dents.			

ORIGINAL JAPANESE AUCTION SHEET

R2 / 4月		メーカー ホンダ		ドア枚数 5	ボディ構造 バン	評価点 4																				
車名 N-VAN		グレード G・ホンダセンシング		駆動区分 4WD																						
車種 自家用・その他 ()	排気量 660 cc	型式 HBD-JJ1	通称 型式	内装 A・B・C																						
車検 - - 年 / 月	燃料 ガソリン	ディーゼル	後日送り品 () 取扱い等 ()																							
走行 82,000 km	シフト AT																									
外装色 ホワイト	カラーNo. (NH906)	エンジン AG・QG・WAG・()	新車品のみ O印 を記入																							
内装色 ()	乗車定員 4人	AW	サンルーフ	車シート																						
左・右 左・右	輸入 区分	ディーラー	並行	ナビ	TV	キーレス																				
セールスポイント		7,510円・預託金																								
マッドプラッタ塗装 16インチ ホール・コントロール・ホンダセンシング 衝突被害軽減ブレーキ 荷室棚 ドライブレコーダー (SD欠) AM/FM ハンズフリー オートエアコン																										
検査記入欄		修復歴 有 ()																								
ルーム内・荷室キズスレ 小キズ小凹		<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみ割れ</td><td>B</td><td>キズ・へこみ</td><td>P</td><td>色あせ・汚れ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>					A	キズ	U	へこみ割れ	B	キズ・へこみ	P	色あせ・汚れ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	へこみ割れ	B	キズ・へこみ	P	色あせ・汚れ	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																	
		登録No. 月 日 までに名義できる方																								
		車検番号 JJ 1-3036448																								
FW	トビ	備A	ワレ	外装	小	ホイール	エアロ	シリアル No.																		
内装	ヨゴレ	シミ	ヤブレ	コガ	コガ穴	オーディオ穴	スレ	長さ cm	幅 cm																	
								高さ cm	最大積重量 kg																	