

2020 MAZDA Carol 5D GL GOO Certified Car		OVERALL R	
		EXTERIOR -	INTERIOR -
MODEL CODE HB36S	DISPLACEMENT 658 cc		
YEAR / REG. 2020/06	MILEAGE 7,725 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Brown		
BODY TYPE Kei			
CHASSIS NO. HB36S-236310	DIMENSIONS (L X W X H) 340 × 148 × 148 cm		
INSPECTOR REPORT			
Exterior: Noticeable scratches and dents have been repaired, but minor ones remain. Interior: Kept clean with no noticeable dirt. Accident history: Signs of impact near the front or rear ends of the frame.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 R2/6月	メーカー マツダ	ドア数 5	ボディ形状 軽四	評価点 R
車名 キャロル	グレード G L ★GOO鑑定証明書★			
車種 自家用	型式 HB36S	排気量 660	燃料 ガソリン	内装 B
車検 9年6月/抹消	走行 7,725マイル	駆動 FWD	エアコン AC	最大積載量 Kg
外装色 ブラウン	カラーNo. ()	リサイクル料 7,930円	販売店 HB36S-236310	
()	シフト インパネ	AT	乗車定員 4人	長さ cm 幅 cm 高さ cm
後日送り品 (保証書・取扱説明書等)	グー鑑定 品質検査報告書 日本自動車流通協会			
装備 ④ ⑤ ⑥ AW サルーフシート ⑦ ⑧ ⑨ ナビ TV キーレス	グー鑑定 コンディションチェックシート X01526G005			
セーلسポイント	鑑定日 2026年7月9日 再鑑定日			
CD/慣性防止装置(ESC)/運転席エアバック/盗難防止システム/キーレスエントリ/A B S/助手席エアバック/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/シートヒーター/ミュージックプレーヤー接続可	車両状態の説明			
査定員記入欄	小 カードサイズ未満 中 A4サイズ未満 大 A4サイズ以上 数値 金額以上			
※ダメージレベルに関する注意事項 傷は記号のみ 小は1 中は2 大は3 例 さす 傷小 ⇒ A へこみ 小 ⇒ U1 さす 傷 ⇒ A2 さす へこみ 大 ⇒ A3	車両状態の図解			
F W ト 2 駆 A フレ 外 輪 A・U A・自 A・フレ 内 装 3 6 0 シ ミ サ プ ル コ デ コ グ イ ヌ スレ	クオリティグレード説明			
外装: 気になるキズやヘコミは補修済みですが、小さなキズやヘコミが残っています。	車両状態の図解			
内装: 気になる汚れ等がない綺麗な室内を保っています。	車両状態の図解			
修復歴: 骨格部位の先端付近、または後端付近に衝撃を受けた形跡があります。	車両状態の図解			