

2020 MAZDA CX-30 1.8 XD L Package Diesel Turbo		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3DA-DM8P	DISPLACEMENT 1,756 cc		
YEAR / REG. 2020/02	MILEAGE 61,145 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE SUV		
CHASSIS NO. DM8P-106552	DIMENSIONS (L X W X H) 440 × 180 × 154 cm		
SALES POINTS			
Alloy Wheels		Power Tailgate	
Leather Seats (Perforated Leather)		Pre-Collision Braking	
Adaptive Cruise Control		Back Camera	
Mazda Harmonic Acoustics (8 speakers)			
INSPECTOR REPORT			
Left center pillar dent. Front glass has scratches, stone chips, cracks, repair marks, and requires replacement. Interior has scratches, dirt, burns, holes, scuffs, tears, and rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 令和2年2月	車名・グレード CX-30 XD Lパッケージ	2WD 4WD	評価点 (R)
ディーラー・並行 モデル年式 ハンドル 左・右	型式 3DA-DM8P	排気量 1800 CC	ドア 5
		定員 5人	積載 kg
		形状 枠	外装内装 B C
車種 自家用	シフト FAT	セールスポイント (正常に機能するものに限りです)	
車検 令和9年2月 (日)	冷房 AC	キーレススマートキー・ETC・バックモニター	
走行 6万1千145 km	燃料 軽油	装備品 (純正品に限り○をつけてください)	
色 レッド	色替 マイ	PS	AW
R券 9,720 円		SR	ナビ
注意事項申告欄	左センターピラー歪み	新車保証書 有・無	後日品
フロントガラス キズ・飛石・ヒビ割・リペア跡・X要	内装 キズ・汚レ・コゲ・穴・スレ・キレ・破レ	スア	
車台番号 106552	登録番号 広島 301 ゆ 7660	A-キズ E-エクボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済	
型式指定番号 参考		類別区分番号 参考	
車検証発行 受・受		備考	