

2020 MAZDA CX-30 2.0 20S Proactive		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-DMEP	DISPLACEMENT 1,997 cc		
YEAR / REG. 2020/11	MILEAGE 25,364 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE SUV		
CHASSIS NO. DMEP-121328	DIMENSIONS (L X W X H) 439 × 179 × 154 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Back Camera Mazda Harmonic Acoustics (8 speakers)		Power Tailgate Adaptive Cruise Control 360° Camera	
INSPECTOR REPORT			
Wheel scratches, door mirror scratches, minor exterior scratches (A) and dents (U), interior dirt, interior trim scratches. Front windshield has scratches, stone chips, cracks, and repair marks, requiring replacement (X). Interior has scratches, dirt, burns, holes, scuffs, tears, and rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 令和2 11 月		車名・グレード CX-30 20S ⁷ プロアクティブ		2WD 4WD		評価点 (4.5)	
ディーラー・並行 型式 5BA-DMEP		排気量 2000		ドア 5		定員 5人	
モデル年式 年 ハンドル 左・右		形状 CC HB		積載 kg		外装 内装 B B	
車種 自家用		シフト FAT		セールスポイント (正常に機能するものに限りです)			
車検 令和9 年 8 月 (日)		冷暖 AAC		スマートキー・全社外アルミホイール・ETC			
走行 2万5千364 km		燃料 ガソリン		キーフリー・エアバック・ETC・コーナーセンサー			
色 グレー		色コード 42S/E23		諸備品 (純正品に限り○をつけてください)			
R券 9,720 円				(PS) (PW) (BS) (AB) AW SR ナビ TV カワ			
注意事項申告欄				新車保証書 後日品 有・無			
ホイール キズ							
ドアミラー キズ							
外装 小A・小U							
室内 汚れ							
内装リ キズ							
フロントガラス キズ・傷・ヒビ割・リペア跡・X要 内装 (キズ・傷・ヒビ割・ヒビ割)・コゲ・穴・スレ・キレ・破れ							
車台番号 121328				A-キズ E-エウボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済			
登録番号 千葉 303 つ 1850				型式認定番号 19358 原付区分番号 0051 全長 439 mm 全幅 179 mm 全高 154 mm			