

2020 MAZDA CX-8 XD L Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3DA-KG2P	DISPLACEMENT 2,188 cc		
YEAR / REG. 2020/01	MILEAGE 89,186 km		
DOORS 5	SEATS 6		
TRANSMISSION AT	FUEL Diesel		
STEERING Right	EXTERIOR COLOR Gray		
BODY TYPE Station Wagon			
CHASSIS NO. KG2P-216901	DIMENSIONS (L X W X H) 490 × 184 × 173 cm		
SALES POINTS			
Alloy Wheels Leather Seats (Nappa Leather) Power Seats (Front) Adaptive Cruise Control Side Camera 360° Camera Bose Sound System (AUDIOPILOT2 + C...		Roof Rails Power Tailgate Pre-Collision Braking Front Camera Back Camera Navigation System	
INSPECTOR REPORT			
Steering wheel scuffs/wear, light interior stains, minor exterior scratches, seat wear and sagging.			

ORIGINAL JAPANESE AUCTION SHEET

R2 / 1月	メーカー マツダ	ドア数 5	ボディ形状 ステーションワゴン	評価点 4
車名 C X - 8	グレード XD Lパッケージ	駆動方式 2WD 4WD		
車種 自家用 ・ その他 ()	排気量 2200 cc	型式 3DA-KG2P	登録区分 A・⑤・C	
年 9	月 1	日 1	扶養 なし	燃料 ガソリン
走行 89,186 km	マイレ 89,186 km	AT	後日進出品 (保証書・取扱説明書等)	
外装色 グレー	カラーNo. ()	エンジン AG・⑤・WAG・()	新車定価 6人	
左・前 左・前 左・前	左・前 左・前 左・前	左・前 左・前 左・前	左・前 左・前 左・前	左・前 左・前 左・前
セールスポイント ★ユーザー買取車★マツダコネクナビ★アルパインフリップダウン★革シート★前席シートH★ベンチレーション★後席シートH★パワーBドア★全方位カメラ		修復歴 有・⑥		
検査記入欄 ハンドルスレやぶれ 内装薄汚れ 外装小傷 シートスレへたり		A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損		
月 日 まで		名義中		
KG2P-216901				
内装 シロ	外装 シロ	ボディ シロ	エンジン シロ	変速機 シロ