

2020 Mitsubishi Delica D5 P		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3DA-CV1W	2,267 cc		
YEAR / REG.	MILEAGE		
2020/03	95,180 km		
DOORS	SEATS		
5	8		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Black	Minivan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
2203838	480 × 180 × 188 cm		
SALES POINTS			
Alloy Wheels		Power Sliding Doors (Both Sides) (Both...	
Power Tailgate		Pre-Collision Braking	
Adaptive Cruise Control		Front Camera	
Side Camera		Back Camera	
Navigation System			
INSPECTOR REPORT			
Interior has minor light dirt, scratches, and dents.			

初年度登録	メーカー 三菱	ドア数 5	ボディ形状 ミニバンワンボックス	駆動方式 FF					
R2 / 3月	車名 デリカD : 5	グレード P	燃費区分 2WD 4WD	9 4.5					
車種 自家用 ・ その他 ()	排気量 2200	CC cc	型式 3DA-CV1W	運転形式 内装 A・C・G					
車検 9年3月抜消	燃料 ガソリン ハイブリッド ()	式 セトル	後付選り品 (保証書・取扱説明書等)						
走行 10万km以上乗入れ受領 * (遠征車・新車)	シフト オート								
外観色 ブラック	カラーNo. AD・600・WAD・()	モデル インパネ AT							
()	内装色 黒色	標準定員 8人	新着商品のみの印刷を記入						
左・右 左・右	輸入国 タイラー	走行距離 13,750 km	エンジン E2000	サドルフ 革シート					
セールスポイント		キーレス							
ユーザー買取・純正10インチナビ・フルセグ・アラウンドビューモニター・レーダークルーズコントロール・両側パワーライドドア・パワーバックドア									
検査記入欄									
内装汚損小A小U									
センサー									
修理履歴									
有。⑤									
A	キズ	U	ヘコみ割れ	B	キズ・ヘコみ	C	熱変形・歪み	G	ガラスの破損
W	修繕跡	S	錆び	C	腐食	X	交換済	XX	交換済
名義人									
月 日 まで名義であること									
車体番号 2203838									
FW	Dトビ	備A	フレ	内装	小	オイル	エアロ		
					A・U	A・油	A・ワレ		
内装	ヨゴレ	シミ	ヤブレ	コゲ	コガ穴	オチ・イボ	ズレ		
最大積載量									