

2020 Mitsubishi ek Wagon M		OVERALL	
		3	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-B33W	DISPLACEMENT 659 cc		
YEAR / REG. 2020/06	MILEAGE 4,637 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Station Wagon		
CHASSIS NO. B33W-0011690	DIMENSIONS (L X W X H) 340 × 148 × 164 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Seat stains, left rear wheel arch outer distortion, interior dirt and scuffs			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R2	メーカー 三菱	ドア枚数 5	ボディ形状 ステーションワゴン	評価点 3																				
6月	車名 eKワゴン	グレード M	駆動区分 4WD																					
車種 自家用・その他 ()	排気量 660 cc	型式 5BA-B33W	通称 型式	内装 A・B・C																				
車検 - - 年 / 月	燃料 ガソリン	ディーゼル	後日送り品 (保証書・取扱説明書 等)																					
走行 4,637 km	シフト インパネ	CVT																						
外装色 シルバー	カラーNo. (U25)	エアコン (A・AAG・WAG・)	新着品のみ O印 を記入																					
内装色 ()	乗車定員 4 人	AW	サンルーフ	革シート																				
左・右 左・右	輸入 区分	ディーラー	走行	8,700円・預託金																				
セールスポイント																								
検査記入欄 シートの染み 左Rタイヤハウスアウトター歪み 室内汚れ・擦れ																								
<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみ/サレ</td><td>B</td><td>キズ/へこみ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>					A	キズ	U	へこみ/サレ	B	キズ/へこみ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	へこみ/サレ	B	キズ/へこみ	P	色あせ/ボケ	G	ガラスキズ															
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済															
登録No. B33W-0011690 月 日 までに名変更できる方 名変更中 車検 最大積載量 Kg																								