

2020 Nissan NV100 Clipper DX GL Package		OVERALL 3.5	
		EXTERIOR -	INTERIOR -
MODEL CODE DR17V	DISPLACEMENT 658 cc		
YEAR / REG. 2020/08	MILEAGE 131,034 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR White		
BODY TYPE Kei			
CHASSIS NO. DR17V-446136	DIMENSIONS (L X W X H) 340 × 148 × 190 cm		
INSPECTOR REPORT			
Seat wrinkles, scratches and dents in the cargo area, uneven repair finish, slight distortion on the left center pillar, core support distortion, and the oil check lamp is on.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R2 / 8月		メーカー 日産		ドア枚数 5		ボディ形状 軽四		評価点 3.5																					
車名 NV100クリッパーバン		グレード DX GL パッケージ		駆動区分 2WD		4WD																							
車歴 自家用・その他(営業用)	排気量 660	型式 DR17V	通称 型式	内装 A・B・C																									
車検 - 年 - 月 / 日	燃料 ガソリン	ディーゼル	後日送り品 (保証書・取扱説明書等)																										
走行 131,034 km	マイル 82	インパネ 4 AT																											
外装色 ホワイト	カラーNo. (26U)	エアコン (A)・AAG・WAG・()		新備品のみ O印 を記入																									
()	内装色	乗車定員 4 人		P3	P4	AW	サンルーフ	革シート																					
ハンド 左・右	輸入 区分	ディーラー	並行	リサイクル料 7,860円	預託金	エアバック	ABS	ナビ	TV																				
セールスポイント																													
検査記入欄				修復歴 有 (5)																									
シートシワ、荷室キズ凹、補修ムラ、左センターピラー小歪、コアサポート歪、オイルチェックランプ点灯				<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ・凹み</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・汚れ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換所</td> </tr> </table>						A	キズ	U	ヘコみ・凹み	B	キズ・ヘコみ	P	色あせ・汚れ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所
A	キズ	U	ヘコみ・凹み	B	キズ・ヘコみ	P	色あせ・汚れ	G	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所																				
登録No.				名義中																									
月 日				まで(に)名義できる方																									
車体 番号 DR17V-446136																													
シリアル No.																													
PW	トランス	備A	フレ	外装	小	ボイル	エアロ																						
内装	ヨコ	シミ	ヤブレ	コゲ	コゲ穴	オーディオ穴	その他	高さ cm	最大積載量 Kg																				