

2020 Nissan NV200 Vanette Van DX		OVERALL	
		3	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE VM20	DISPLACEMENT 1,597 cc		
YEAR / REG. 2020/11	MILEAGE 68,853 km		
DOORS 5	SEATS 2		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Minivan		
CHASSIS NO. VM20-163365	DIMENSIONS (L X W X H) 440 × 170 × 186 cm		
SALES POINTS			
Back Camera		Navigation System	
INSPECTOR REPORT			
Exterior AU grade, interior dirt and scuffs, cargo area scratches and dents, carpet scuffs, right rear instrument panel repaired, right rear corner panel repaired, E-grade scratches and scuffs, interior dirt, power window stone chips			

ORIGINAL JAPANESE AUCTION SHEET

R2 / 11月		メーカー 日産		ドア枚数 5	ボディ形状 バン	評価点 3																				
車名 NV200バネットバン		グレード DX		駆動区分 2WD		4WD																				
車種 自家用・その他 ()	排気量 1600 cc	型式 VM20	燃料 種類 混合	変速機 型式 AT	内装 A・B・C																					
走行 68,853 km	フロア	AT	後日選り品 (保証書・取付品等)																							
外装色 ホワイト	カラーNo. 00	エンジン AAG・WAG・	整備品のみ O印 を記入																							
内装色 ()	定員 2人	2人	AW	サンルーフ	革シート																					
左・右 輸入 区分	ディーラー	走行 7,460円	エレクトロニクス	AW	サンルーフ	革シート																				
セールスポイント																										
CD/バックカメラ/ETC/運転席エアバック/キーレスエントリー/A B S /メモリーナビ他			修復歴 有・無																							
検査記入欄			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみ/割れ</td><td>B</td><td>キズ・へこみ</td><td>P</td><td>色あせ・汚れ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>燃費</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換部</td><td>XX</td><td>交換部</td> </tr> </table>				A	キズ	U	へこみ/割れ	B	キズ・へこみ	P	色あせ・汚れ	G	ガラスキズ	W	燃費	S	サビ	C	腐食	X	交換部	XX	交換部
A	キズ	U	へこみ/割れ	B	キズ・へこみ	P	色あせ・汚れ	G	ガラスキズ																	
W	燃費	S	サビ	C	腐食	X	交換部	XX	交換部																	
外装AU 室内汚れスレ 荷重キズ凹 カーパーツスレ 右Rコーナーパネル加飾虫 キズ・スリキズ			名義中																							
車体番号 VM20-163365			月 日 までに名義できる方																							
FW 000			シリアル No.																							
内装 000			重量 000 kg																							