

2020 RX Hybrid Lexus RX 3.5 RX450h_F Sport 4WD		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DAA-GYL25W	DISPLACEMENT 3,456 cc		
YEAR / REG. 2020/03	MILEAGE 37,757 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE SUV		
CHASSIS NO. GYL25-0021578	DIMENSIONS (L X W X H) 489 × 189 × 171 cm		
SALES POINTS			
Alloy Wheels Leather Seats Adaptive Cruise Control Navigation System		Sunroof Power Tailgate 360° Camera Lexus RX Premium Sound System (12 s...	
INSPECTOR REPORT			
Exterior has minor A and U marks. Wheels have scratches. Seats have wrinkles. Trunk has scratches. Front glass has scratches, stone chips, cracks, repair marks, and requires replacement. Interior has scratches, stains, burns, holes, scuffs, tears, and rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 令和2 3 月		車名・グレード RXハイブリッド RX450h_Fスポーツ		2WD (4WD)	評価点 (4.5)
ディーラー・並行 型式 DAA-GYL25W		排気量 3500	ドア 5	定員 5人	外装内装 B B
モデル年式 年 ハンドル 左・右		CC 3500	形状 HB	積載 kg	
車種 自家用		シフト FAT		セールスポイント (正常に機能するものに限りです)	
車検 年 月 (日)		冷暖 AAC		スマートキー・ETC	
走行 3万7千757 km		燃料 その他		メモリーナビ、フルセグTV、全方視カメラ	
色 パール		色コード 083/LC26		諸備品 (純正品に限り○をつけてください)	
R券 13,330 円				(PS) (PW) (BS) (AB) (AW) (SR) ナビ TV カワ	
注意事項申告欄				新車保証書 有・無	
外装 小A・小U					
ホイール キズ					
シートシワ					
荷室 キズ					
フロントガラス キズ・飛石・ヒビ割・リペア跡・X要 内装 (キズ)・汚レ・コゲ・穴・スレ・キレ・破レ					
車台番号 0021578					
登録番号					

A-キズ	E-エウボ	U-凹み	W-補修跡	S-サビ	C-腐食	XX-交換済
型式指定番号 00186	車検区別番号 0057	長さ 489	幅 189	高さ 171		