

2020 RX RX300 "F SPORT"		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3BA-AGL20W	1,998 cc		
YEAR / REG.	MILEAGE		
2020/08	57,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Other	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
AGL20-0017961	489 × 190 × 171 cm		
SALES POINTS			
Alloy Wheels		Leather Seats (Leather)	
Power Tailgate		Adaptive Cruise Control	
360° Camera		Navigation System	
Lexus RX Premium Sound System (12 s...			
INSPECTOR REPORT			
Exterior: Noticeable scratches and dents have been neatly repaired, but minor ones may remain. Interior: Some noticeable stains are present in parts. Accident History: No frame damage.			

許可登録番号 R2 8月		メーカー レクサス		ドア数 5		ボディ形状 SUV/クロカン		評価点 5	
車名 R X		グレード RX300 "F SPORT"							
車種 自家用		駆動方式 右		3BA-AGL20W		年式 2000		燃費 ガソリン	
年式 - 年 - 月 / 日		走行距離 57,000 マイル		車庫 AC		車庫 AC		車庫 AC	
住所 ソウゴウビル		カラーNo.		リサイクル料 12,680円		車台番号 AGL20-0017961			
()		シフト アロ		定価 AT		乗車 5人		長さ cm	
重量 kg		長さ cm		高さ cm		幅 cm		重量 kg	

車検

検査項目

点検項目

検査結果

検査場所

検査日時

検査者

検査結果

検査場所

検査日時

検査者

車検合格の証明

検査項目

点検項目

検査結果

検査場所

検査日時

検査者

検査結果

検査場所

検査日時

検査者

車検合格の証明

検査項目

点検項目

検査結果

検査場所

検査日時

検査者

検査結果

検査場所

検査日時

検査者

車検合格の証明

検査項目

点検項目

検査結果

検査場所

検査日時

検査者

検査結果

検査場所

検査日時

検査者