

2020 SUBARU Sambar Van Transporter Smart Assist		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
S331B	658 cc		
YEAR / REG.	MILEAGE		
2020/04	50,000 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Silver	Minivan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
S331B-0020781	340 × 148 × 188 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Interior scratches and dirt, seat scuffs and wrinkles, exterior minor and light scratches, cargo area scratches, scuffs and dirt, studless tires.			

ORIGINAL JAPANESE AUCTION SHEET

R2 / 4月		メーカー スバル		ドア枚数 5	ボディ形状 バン	評価点 4																														
車名 サンバーバン		グレード トランスポーター スマートアシスト		駆動区分 2WD	4WD																															
車種 自家用・その他(レンタカー)	積気量 660	型式 S331B	通称型式	内装 A・B・C																																
車検 -	年 -	月 -	燃料 ガソリン	ディーゼル	後付選り品(保証書・取扱説明書等)																															
走行 50,000 マイル		インパネ	AT																																	
外装色 シルバー	カラーNo.	エアコン	Qb・AAG・WAG・()	装備品のみ O印 を記入																																
()	内装色	乗車定員 4 人	PS	AW	サンルーフ	革シート																														
左・右	左・右	ディーラー・並行	7,510円・預託金	エブリック	ABS	TV																														
セールスポイント CD/バックカメラ/ETC/横滑り防止装置(ESC)/運転席エアバック/キーレスエントリー/ABS/助手席エアバック/メモリーナビ他/衝突被害軽減ブレーキ/4WD/アイドリングストップ/両側スライド																																				
検査記入欄 内装キズ、汚れ シートスレ、シワ 外装キズ、薄キズ 荷室キズ、スレ、汚れ スタッドレスタイヤ																																				
<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ/ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>Q</td><td>ガラスキズ</td></tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td></tr> <tr> <td colspan="10"> 登録No. _____ 月 _____ 日 _____ までにも名実できる方 車体番号 S331B-0020781 シリアル No. _____ 重量 cm cm cm kg </td> </tr> </table>							A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済	登録No. _____ 月 _____ 日 _____ までにも名実できる方 車体番号 S331B-0020781 シリアル No. _____ 重量 cm cm cm kg									
A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラスキズ																											
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																											
登録No. _____ 月 _____ 日 _____ までにも名実できる方 車体番号 S331B-0020781 シリアル No. _____ 重量 cm cm cm kg																																				